

Motor Appraiser and Insurance Loss Adjustor Blk 361 Yung An Road #12-105 Singapore 610361 Mobile: +65 9232 0012 Email: iconappraiser@gmail.com UEN.: 202006885Z

INVOICE

To

: DIRECT FUNERAL SERVICES PTE LTD

Date

: 18 Nov 2022

c/o

: Celebrity Auto

176 Sin Ming Drive #03-17

Invoice No.

: 2022-00182

Sin Ming Autocare

Ref

: 20221118/00182/CA

Singapore 575721

	DESCRIPTION	AMOUNT
Service rendere	d for appraisal / inspection report :	
Professional	inspection fees	SGD 800.00
Singapore dollar	Total : EIGHT HUNDRED ONLY.	SGD 800.00
Registration no.	: YG99H	
Make/Model		
Our reference		
All payments made p	ayee to:- PRAISER PTE LTD"	
	:- 30 days from invoice date	

for ICON MOTOR APPRAISER PTE LTD



Motor Appraiser and Insurance Loss Adjustor Blk 361 Yung An Road #12-105 Singapore 610361 Mobile: +65 9232 0012 Email: iconappraiser@gmail.com UEN.: 202006885Z

INSPECTION REPORT

To : DIRECT FUNERAL SERVICES PTE LTD

Our ref. : 20221118/00182/CA

Date : 18 Nov 2022

REFERENCE

Assign by : DIRECT FUNERAL SERVICES PTE LTD

3rd party Veh. : SKL8329G
Inspection on : 22 Sep 2022
Accident on : 26 Aug 2022
Workshop name : Celebrity Auto

Inspection at : 176 Sin Ming Drive #03-17

Sin Ming Autocare Singapore 575721

PARTICULARS OF DAMAGED VEHICLE

Registration no. : YG99H Odometer : 59280 km Make / Model : MITSUBISHI CANTER FEB21ER4SDEB Chassis no. : FEB21EA20166 Regn. date : 2016 Engine no. : 4P10B96738 Body colour : White Engine cap. : 2998 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering : In order Paintwork : Fair

Footbrake : In order Undercarriage : Serviceable

Handbrake : In order Gen. condition : Fair

TYRE CONDITION ON VEHICLE

		Make	Size	Tread depth	Type of road wheel
Front N/S	:	Yokohama	195/85R15	70%	Steel
Front O/S	:	Yokohama	195/85R15	70%	Steel
Rear N/S	:	Yokohama	195/85R15	70%	Steel
Rear O/S	:	Yokohama	195/85R15	70%	Steel


NOTE: Tread depth percentages represents the visually estimated remaining life of tyre treads.

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

20221118/00182/CA Page 1 of 2

POINT OF IMPACT

The damages was found on the front and rear portions.



RECOMMENDATION

The estimated cost of repair submitted by the repairer Celebrity Auto as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairer have agreed to undertake the **part by part** repairs at our recommendation.

Our adjusted cost of repair is SGD 26,904.45 to carry out the repairs. Kindly refer to parts and labour portion for a detailed account of the cost estimates.

REMARKS

However, for your information, under normal circumstances, the repair normally would take approximately 12 (Twelve) working days to complete.

We have **NOT AUTHORISED** the repair to the damaged vehicle. The survey was conducted strictly on a "WITHOUT PREJUDICE" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our final report, which includes material damages photographs.

Yours faithfully, ICON Motor Appraiser Pte Ltd

Ng Chek Sim

Motor Vehicle Appraiser

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

S/N	Parts description	OTV	Constitution	-		
1		QTY	Condition		irer's Estimate	ecommendation
15000	L/R front bumper guard	2	Damaged	\$	320.00	\$ 320.00
2	Front bumper	1	Damaged	\$	980.00	\$ 980.00
3	Towing hook set	1	Bent	\$	275.00	\$ 275.00
4	L/R Headlamp	2	Damaged	\$	1,309.30	\$ 1,309.30
5	L/R side lamp	2	Damaged	\$	627.60	\$ 627.60
6	L/R signal lamp	2	Damaged	\$	567.90	\$ 567.90
7	Radiator grille	1	Damaged	\$	1,102.80	\$ 1,102.80
8	Driver door side step	1	Damaged	\$	180.00	\$ 180.00
9	Passenger door side step	1	Damaged	\$	180.00	\$ 180.00
10	A/C condenser	1	Damaged	\$	680.00	\$ 680.00
11	A/C condenser bracket	1	Bent	\$	160.00	\$ 160.00
12	A/C dryer bracket	1	Bent	\$	80.00	\$ 80.00
13	A/C dryer	1	Damaged	\$	160.00	\$ 160.00
14	Fan motor	1	Malfunction	\$	550.00	\$ 550.00
15	Fan motor blade	1	Damaged	\$	320.00	\$ 320.00
16	Fan motor cowling	1	Damaged	\$	220.00	\$ 220.00
17	A/C pressure pipe	1	Bent	\$	240.00	\$ 240.00
18	Front bumper stay L/R	4	Distorted	\$	600.00	\$ 600.00
			Subtotal	-	8,552.60	\$ 8,552.60
		25.00%	\$	-	\$ 2,138.15	
		\$	8,552.60	\$ 6,414.45		

•	ial nett items						
No.	Parts description	QTY	Condition	Rep	airer's Estimate	Our R	ecommendation
1	LH taillamp	1	Damaged	\$	350.00	\$	320.00
2	LH taillamp panel	1	Damaged	\$	300.00	\$	250.00
3	LH cargo conceal door w hinge,lock	1	Damaged	\$	5,800.00	\$	5,500.00
4	Rear cross wood on floor board rear portion	1	Damaged	\$	3,200.00	\$	2,800.00
5	Rear angle bar frame on rear floor board	1	Damaged	\$	2,200.00	\$	1,900.00
6	Custom rear reinforcement galvanized T bar	1	Bent	\$	1,800.00	\$	1,600.00
7	Front steel wheel n/s	1	Damaged	\$	580.00	\$	550.00
8	Front tyre 12 ply n/s	1	Damaged	\$	450.00	\$	420.00
9	Taillamp clips	8	Necessary	\$	64.00	\$	50.00
10	Taillamp panel sealant	1	Necessary	\$	100.00	\$	80.00
11	Tailgate custom sticker logos	1	Necessary	\$	1,500.00	\$	1,400.00
12	F/R licence plate	2	Damaged	\$	160.00	\$	80.00
			Total	\$	16,504.00	\$	14,950.00

Labo	our					
No.	Description	QTY	Repa	airer's Estimate	Our R	ecommendation
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	1	\$	2,200.00	\$	2,000.00
2	To disconnect wire harnesses of electrical components to facilitate repairs, reconnect and check functions.	1	\$	380.00	\$	300.00
3	To remove & refit both front wheels to facilitate replacement & check for damages.	1	\$	250.00	\$	200.00
4	To perform brake testing.	1	\$	200.00	\$	180.00
5	To refit & perform side slip test after replacement / checks is performed.	1	\$	200.00	\$	160.00
6	To remove and refit a/c condenser for replacement. To recharge system & check a/c functionality.	1	\$	480.00	\$	450.00
7	Supply spray paint material and necessary items to respray affected area / panel.	1	\$	2,200.00	\$	2,000.00
8	To rust proof all affected portions after repair.	1	\$	300.00	\$	250.00
		Total labour	\$	6,210.00	\$	5,540.00

Estimate Grand Total	\$	31,266.60	\$ 26,904.45
	-	The second secon	

Our Ref:

20221118/00182/CA

Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.


Our Ref:

20221118/00182/CA

Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:


20221118/00182/CA

Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:




Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA


Your Ref:



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref: 20221118/00182/CA

Your Ref: SKL8329G



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:




Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:














Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:




Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20221118/00182/CA

Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.