

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22012421/NYA3Q2**Date:** 27/06/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001050680
Claimant Vehicle No :	SHD3966C	Insured Vehicle No :	GBG6263H
Date of Loss:	09/12/2022	Nature of Claim:	TP
		Claim No:	202222008780/FR

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3966C		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2C27081
Reg. Date:	31/05/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU003081255
Colour:	Blue	Odometer:	338455 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	Davanti 4 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	Davanti 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,762.28	3,172.71	3,589.57	53.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,680.00	1,220.00	42.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,662.28	4,852.71	4,809.57	49.78
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	9,662.28	3,900.00	5,762.28	59.64
+ GST 8.00/8.00% (S\$)	772.98	312.00	460.98	59.64
Nett Amount (S\$)	10,435.26	4,212.00	6,223.26	59.64
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Car Rental (6.0 x S\$129.68/day) (S\$)		778.08		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,292.08		

INSPECTION

Date of Assignment:	12/12/2022	
Date Inspected:	12/12/2022	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days	

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2023)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3966C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK COVER	Serviceable	1,303.29 FL	*- FL
2	1		*REAR TRUNK OUTER GARNISH	Repair	1,054.71 FL	*- FL
3	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	62.14 FL	*62.14 FL
4	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	62.14 FL	*62.14 FL
5	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	81.43 FL	*81.43 FL
6	1		*REAR BUMPER	Repair	503.04 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Dented	378.32 FL	*378.32 FL
8	1		*REAR BUMPER LOWER COVER -BLACK	Deformed	654.96 FL	*654.96 FL
9	2		*REAR BUMPER EXTENSION RH/LH	Serviceable	464.00 FL	*- FL
10	2		*REAR BUMPER SIDE BRKT LH/RH	Serviceable	225.40 FL	*- FL
11	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
12	1		*REAR BUMPER TOW COVER	Deformed	82.70 FL	*82.70 FL
13	1		*FRONT BUMPER	Repair	586.16 FL	*- FL
14	10		*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
15	1		*FRONT BUMPER UPPER GRILLE	Serviceable	301.90 FL	*- FL
16	1		*FRONT GRILLE H EMBLEM	Cracked	87.10 FL	*87.10 FL
17	1		*FRONT LICENSE PLATE GARNISH	Cracked	99.00 FL	*99.00 FL
18	1		*REVERSE SENSOR	Serviceable	135.70 FS	*- FS
19	1		*REAR TRUNK COMFORTDELGRO	Necessary	30.00 FS	*30.00 FS
20	1		*REAR TRUNK 65521111	Necessary	30.00 FS	*30.00 FS
21	1		*REAR TRUNK APPS	Necessary	40.00 FS	*40.00 FS
22	1		*REAR BUMPER ADV STICKER	Necessary	50.00 FS	*50.00 FS
23	2		*REAR FENDER ADV STICKER LH/RH	Necessary	200.00 FS	*200.00 FS
24	2		*WINDSCREEN SEALANT	Not Necessary	92.00 FS	*- FS
25	1		*FRONT NO PLATE WITH TRIM COVER	Deformed	55.00 FS	*55.00 FS
26	1		*BOOTLID SPOILER	Cracked	1,787.79 FL	*1,787.79 FL
27	1		*BOOTLID THIRD BRAKE LAMP	Cracked	394.70 FL	*394.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,805.48	4,095.28
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,043.20	922.57
Total Parts (\$\$)	6,762.28	3,172.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING -FRONT & REAR	New	1,200.00	950.00
2	SPRAY PAINTING CHARGE -FRONT & REAR	New	1,200.00	650.00
3	WIRING CHARGE	New	40.00	0.00
4	TUFF KOTE	New	100.00	50.00
5	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
6	R/I REAR WINDSCREEN GLASSES	New	240.00	0.00
Gross Labour Cost (S\$)			2,900.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >