

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2300885

3 ANSON ROAD #16-00 INV Date 15/02/2023 SPRINGLEAF TOWER Reference CC3/CTI22

SPRINGLEAF TOWER Reference CC3/CTI22012423/Npa3q2 SINGAPORE 079909

Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 3079D

Insured Veh. SGS 8823G

Claim No. SNM22D208758/C02

Policy No. DMPNSNW00014812200

Accident Date 06/12/2022

Inspection Date 07/12/2022

| Description | Total |
|--------------------------------|--------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (8%) | 32.00 |
| Grand Total | 432.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|-----|---|---|-----------------|--------|------------------------|--|--|
| | CHINA TAIPING IN | SURANCE (S) PTE LTD | | Ref: | CC3/CTI22012423/Npa3q2 | | |
| | 3 ANSON ROAD # SPRINGLEAF TOV | 16-00 VERSINGAPORE 079909 | | Date: | 15/02/2023 | | |
| | | | | Code: | СТІ | | |
| 1. | | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SGS 8823G | Veh. Inspected | k | SHA 3079D | | |
| | Policy No. | DMPNSNW00014812200 | Coverage (\$) | | 0.00 | | |
| | Claim No. | SNM22D208758/C02 | Excess (\$) | | 0.00 | | |
| | Assign From | | Assign Date | | 07/12/2022 | | |
| 2. | | Vehicle Partic | culars & Condit | ion | | | |
| | Make & Model | HYUNDAI IONIQ | c.c | | 1580 | | |
| | Engine No. | HIDDEN | Year of Reg. | | 2019 | | |
| | Chassis No. | KMHC851CVLU187202 | Colour | | BLUE | | |
| | Odometer | 271514 KM | Steering | | IN ORDER | | |
| | Brakes | IN ORDER | Modification | | STANDARD ALLOY RIM | | |
| | General | FAIR | | | | | |
| 3. | | Conditi | ons of Tyres | | | | |
| | | Size | Make | | Balance | | |
| | R/H Front Tyre | 195/65 R15 | MOZZA | | 5 mm | | |
| | L/H Front Tyre | 195/65 R15 | MOZZA | | 5 mm | | |
| | R/H Rear Tyre | 195/65 R15 | MOZZA | | 5 mm | | |
| | L/H Rear Tyre | 195/65 R15 | MOZZA | | 5 mm | | |
| 4. | | Description | on of Damages | | | | |
| | THE VEHICLE SU | STAINED DAMAGES AT THE RE | AR PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | | | |
| 5. | | Genera | I Information | | | | |
| | Accident Date | 06/12/2022 | Inspection Date | te | 07/12/2022 | | |
| | Survey held at | COMFORTDELGRO ENGINEER | RING PTE LTD | | | | |
| | | 59 LOYANG DRIVE SINGAPORE 508969 | | | | | |
| 5a. | | Re | emarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | | |
| 5b. | Estimate Days of Repair | | | | | | |
| | ESTIMATED NOR | MAL PERIOD FOR REPAIR: | | 2 Work | ing Days | | |
| | | | <u> </u> | | | | |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3079D

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | COVER -RR BUMPER | TO REPAIR SEE LABOUR | 459.40 | - |
| 1 | MOULDING ASSY -RR BUMPER C | CRACKED | 451.25 | 451.25 |
| 10 | BUMPER COVER CLIP REAR | NOT NECESSARY | 22.00 | - |
| 1 | CAP -RR HOOK | DEFORMED | 98.80 | 98.80 |
| | LESS 20% DISCOUNT | | -206.29 | -110.01 |
| | | | 825.16 | 440.04 |
| | SPECIAL NETT ITEMS | | | |
| 1 | REVERSE SENSOR ASSY (SN) | SERVICEABLE | 180.00 | - |
| | | | 180.00 | - |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING.INCLUSIVE OF THE REPAIR OF COVER - RR BUMPER . | | 400.00 | 350.00 |
| | SPRAYPAINT CHARGE. | | 300.00 | 250.00 |
| | REMOVE/REFIX REVERSE SENSOR . | | 50.00 | 30.00 |
| | | | 750.00 | 630.00 |
| | GRAND TOTAL | | 1,755.16 | 1,070.04 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | 850.00 |
|--------------------------------------|--------|
| (TO ITS PRE-ACCIDENT CONDITION) | |

Report Ref No. CC3/CTI22012423/Npa3q2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

Amonto

HO LEONG CHUAN

Automotive Assessor



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 3079D

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 3079D

RE-INSPECTION





