

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012430/AQP3Q2**Date:** 02/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00017352200

Claimant Vehicle No : SKU6117S **Insured Vehicle No :** SNC9532R

Date of Loss: 07/12/2022 Nature of Claim: TP Claim No: SNM22D208867/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU6117S**

Make & Model: TOYOTA HARRIER, 2.0 (A) Engine No: 3ZRB590015

Reg. Date: 04/08/2015 (Man. Year: 2015) Chassis No: ZSU600049578

Colour: Black Odometer: 114260 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55 R19 Rear Tyre Size: 255/55 R19

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,236.55	6,582.30	8,654.25	56.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,040.00	930.00	2,110.00	69.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,276.55	7,512.30	10,764.25	58.90
Approved Total (Overridden) (\$\$)		6,000.00		
Nett Amount (\$\$)	18,276.55	6,000.00	12,276.55	67.17

INSPECTION

Date of Assignment: 27/02/2023

Date Inspected: 28/12/2022 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2023)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU6117S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,480.10 FL	*1,330.00 FL
2	2		*FRONT BUMPER FOG LAMP	Not Necessary	718.20 FL	*- FL
3	1		*FRONT BUMPER FOG LAMP COVER	O/S Cracked	220.20 FL	*110.10 FL
4	1		*FRONT BUMPER LOWER LIP	Not Necessary	378.10 FL	*- FL
5	1		*FRONT BUMPER CENTER BEAM	Bent	276.10 FL	*276.10 FL
6	1		*FRONT BUMPER SIDE BEAM RH	Not Necessary	59.40 FL	*- FL
7	1		*FRONT BUMPER SIDE SPONGE RH	Cracked	108.60 FL	*108.60 FL
8	1		*FRONT BUMPER LOWER GRILLE	Deformed	365.00 FL	*365.00 FL
9	1		*FRONT BUMPER BOTTOM GARNISH	Not Necessary	187.10 FL	*- FL
10	2		*FRONT BUMPER TOWING HOOD	Deformed	76.20 FL	*76.20 FL
11	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	196.20 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	490.60 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT CENTER SPONGE	Cracked	142.30 FL	*142.30 FL
14	1		*HEADLAMP HID	O/S Cracked	7,060.20 FL	*3,530.10 FL
15	2		*HEADLAMP LOWER BRACKET	Not Necessary	102.20 FL	*- FL
16	2		*HEADLAMP LOWER BRACKET SPONGE	Not Necessary	217.20 FL	*- FL
17	1		*FRONT FENDER RH	Repair	972.50 FL	*- FL
18	2		*FRONT FENDER QUARTER COVER	Not Necessary	236.60 FL	*- FL
19	1		*FRONT FENDER COWLING RH	Not Necessary	421.10 FL	*- FL
20	1		*CENTER GRILLE	Cracked	986.30 FL	*598.00 FL
21	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	336.70 FL	*- FL
22	1		*FRONT SUPPORT PANEL	Not Necessary	796.80 FL	*- FL
23	1		*FRONT BRACE PANEL	Not Necessary	247.70 FL	*- FL
24	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
25	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
26	1		*SET FRONT BUMPER BOTTOM GARNISH CLIP	Not Necessary	30.00 FS	*- FS
27	1		*SET FRONT BUMPER LOWER GRILLE CLIP	Necessary	30.00 FS	*20.00 FS
28	1		*FRONT BUMPER LOWER SPOILER (MODELLISTA)	Cracked	2,800.00 FS	*1,600.00 FS
29	1		*SET FRONT FENDER COWLING CLIP	Not Necessary	60.00 FS	*- FS
30	1		*SET FRONT PANEL BOTTOM COVER GARNISH CLIP	Not Necessary	30.00 FS	*- FS
31	1		*SET RADIATOR GRILLE CLIP	Necessary	30.00 FS	*30.00 FS
32	1		*SET AIR GUARD GARNISH CLIP	Not Necessary	40.00 FS	*- FS
33	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	30.00 FS	*- FS
34	1		*SET FRONT PANEL BOTTOM COVER GARNISH CLIP	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,255.40	8,216.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,018.85	1,634.10
Total Parts (\$\$)	15,236.55	6,582.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,400.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	500.00
3	REFOCUS HEADLAMP BEAM	New	80.00	30.00
4	REMOVE AND REFIX AIRCON COMPRESSOR AND REFILL GAS	New	180.00	0.00
5	REMOVE AND REFIX AIRCON CONDENSOR	New	120.00	0.00
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			3,040.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >