

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012431/UVP3E2**Date:** 09/02/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00001402201
Claimant Vehicle No :	SKU5379J	Insured Vehicle No :	SFQ2232Z
Date of Loss:	07/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D208825/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU5379J	Engine No:	CXS150497
Make & Model:	VOLKSWAGEN GOLF, 1.4 A7 TSI (A)	Chassis No:	WVWZZZAUZFW283677
Reg. Date:	31/07/2015 (Man. Year: 2015)	Odometer:	90607 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,382.35	5,898.90	1,483.45	20.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,615.00	1,690.00	925.00	35.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,997.35	7,588.90	2,408.45	24.09
Approved Total (Overridden) (S\$)		6,050.00		
(S\$)	9,997.35	6,050.00	3,947.35	39.48
+ GST 7.00/7.00% (S\$)	699.81	423.50	276.31	39.48
Nett Amount (S\$)	10,697.16	6,473.50	4,223.66	39.48

INSPECTION

Date of Assignment:	10/01/2023		
Date Inspected:	09/01/2023	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Feb 2023)
Parts:	143	VOLKSWAGEN GOLF 1.4 A7 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU5379J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,256.55 FL	*1,256.55 FL
2	2		*REAR BUMPER SIDE RETAINER - LH / RH	Not Necessary	96.30 FL	*- FL
3	1		*SET REAR BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	655.95 FL	*655.95 FL
5	2		*REAR BUMPER CENTRE BRACKET - LH / RH	Cracked	169.00 FL	*169.00 FL
6	1		*REAR BUMPER TOW COVER	Not Necessary	33.65 FL	*- FL
7	1		*SET REAR BUMPER SENSOR - LH / RH	Shorted	797.30 FN	*200.00 F
8	2		*REAR BUMPER NUMBER PLATE LAMP - LH / RH	Not Necessary	96.50 FL	*- FL
9	1		*REAR BUMPER LOWER (BLACK)	Grazed	398.05 FL	*398.05 FL
10	2		*REAR TAILLAMP LOWER RETAINER - LH / RH	Not Necessary	96.30 FL	*- FL
11	1		*REAR BOOT	Badly Dented	1,838.60 FL	*1,838.60 FL
12	2		*REAR BOOT HINGE - LH / RH	Not Necessary	227.50 FL	*- FL
13	2		*REAR BOOT ABSORBER - LH / RH	Not Necessary	235.00 FL	*- FL
14	1		*REAR BOOT TSI WORDING	Necessary	68.15 FL	*68.15 FL
15	1		*REAR BOOT GOLF WORDING	Necessary	94.35 FL	*94.35 FL
16	1		*REAR BOOT VW EMBLEM	Not Necessary	120.75 FL	*- FL
17	1		*REAR BOOT BLUE MOTION TECHNOLOGY WORDING	Necessary	66.95 FL	*66.95 FL
18	1		*REAR BOOT LOCK	Twisted	273.75 FL	*273.75 FL
19	1		*REAR BOOT RUBBER	Twisted	337.40 FL	*337.40 FL
20	1		*REAR PANEL	Dented	1,037.25 FL	*1,037.25 FL
21	1		*REAR PANEL TOP GARNISH	Not Necessary	161.65 FL	*- FL
22	1		*REAR NUMBER PLATE WITH CASING	Bent	45.00 FS	*40.00 FS
23	2		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
24	1		*REAR WINDSCREEN SPONGE TAPE	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	8,190.95	6,521.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	728.87	622.10
- Nett Item Discount on N Items 10.00/0.00% (\$\$)	79.73	0.00
Total Parts (\$\$)	7,382.35	5,898.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS, CUT/WELD PANEL, REMOVE, REPLACE ACCIDENT PARTS	New	900.00	600.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	900.00	700.00
3	TO CHECK WIRING	New	40.00	20.00
4	TO REMOVE, REPLACE REAR BUMPER SENSOR	New	120.00	50.00
5	TO REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New	150.00	80.00
6	TO TUFF-KOTE	New	75.00	60.00
7	TO RESET CHECK LIGHT	New	200.00	0.00
8	TO REMOVE, REFIX REAR WINDSCREEN	New	150.00	120.00
9	TO TRANSFER REAR BOOT AND REAR BOOT FITTINGS	New	80.00	60.00
Gross Labour Cost (\$\$)			2,615.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >