



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
xxAXA INSURANCE PTE LTD (nka:HSBC LIFE (S) PTE LTD ) 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: CYNTHIA LOH			Ref: CS/ASM22008948/Uny3e2 Date: 30/09/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJT 6553H	Veh. Inspected	SKW 4952A	
Policy No.		Coverage (\$)	0.00	
Claim No.	S2M04ATH	Excess (\$)	0.00	
Assign From	CYNTHIA LOH	Assign Date	12/09/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLKSWAGEN GOLF A7 1.4 (A)	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WVWZZZAUZFW356402	Colour	WHITE	
Odometer	84285 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	GOODYEAR	6 mm	
L/H Front Tyre	225/45 R17	GOODYEAR	6 mm	
R/H Rear Tyre	225/45 R17	GOODYEAR	6 mm	
L/H Rear Tyre	225/45 R17	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/09/2022	Inspection Date	12/09/2022	
Survey held at	2ND AUTO PTE LTD 15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	