



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                         |  |   |   |            |
|---|--|---|---|------------|
| STRIDES AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK<br>E4SINGAPORE 757705 |  |   | Ref: CS/SMR22012440/Tvy3m4<br>Date: 19/05/2023<br>Code: SMR |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |  |   |   |            |
|   | Insured Veh.   | SHB 699D  | Veh. Inspected  | FBT 6240E  |
|   | Policy No.   |   | Coverage (\$)   | 0.00       |
|   | Claim No.  | TAX/12/22/2015  | Excess (\$)   | 0.00       |
|   | Assign From  | HUA YEN   | Assign Date   | 13/12/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |   |   |            |
|   | Make & Model   | HONDA ADV150  | c.c   | 149        |
|   | Engine No.   | HIDDEN  | Year of Reg.  | 2021       |
|   | Chassis No.  | MH1KF6112MK034365   | Colour  | GREY       |
|   | Odometer   | 15937 KM  | Steering  | IN ORDER   |
|   | Brakes   | IN ORDER  | Modification  | NIL        |
|   | General  | GOOD  |   |            |
| <b>3. Conditions of Tyres</b>   |  |   |   |            |
|   |  | Size  | Make  | Balance    |
|   | R/H Front Tyre   | 110/80 R14  | FEDERAL   | 5 mm       |
|   | L/H Front Tyre   |   |   | mm         |
|   | R/H Rear Tyre  | 130/70 R13  | FEDERAL   | 5 mm       |
|   | L/H Rear Tyre  |   |   | mm         |
| <b>4. Description of Damages</b>  |  |   |   |            |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.<br>DAMAGES SEE DETAILS.   |   |   |            |
| <b>5. General Information</b>   |  |   |   |            |
|   | Accident Date  | 06/12/2022  | Inspection Date   | 14/12/2022 |
|   | Survey held at   | BIKE PRODUCTION PTE LTD<br>610 SERANGOON ROAD<br>SINGAPORE 218216 |   |            |
| <b>5a. Remarks</b>  |  |   |   |            |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |   |            |
| <b>5b. Estimate Days of Repair</b>  |  |   |   |            |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | 3 Working Days  |            |