

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLR 480M*at Workshop m/s *C&C 10am*

of _____

Insured: *GBB 5786Z*

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: *860k*

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: *6*

days

Res.: Yes or No

Lum Sum: *1-3.1*

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

2356

Vehicle: IN / OUT

Date: _____

Person Contacted: *L7A 31639*Veh No: *SLR 480M*Yr Regn: *17/08/17*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CA*Make: *Kia Cerato*c.c. *1591*Colour: *White*

A/C: Insured / Std / NI / NA

Sp. Reading: *81516*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *KNAPZ411MJ5739490*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: *215/45-R17*

BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMIT

TOYO / YOKO or *roadstone*

Front

Rear

R/Bal. *6*

mm

R/Bal. *6*

mm

L/Bal. *6*

mm

L/Bal. *6*

mm

D.O.A. *11/12/22*D.O.I. *21/12/22*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time

Action / Instruction

*on 11k.**5/1/23 11/1 10409.00 inland merger.*

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

) S + RS. SI

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lee Chun Ping (li Junbin)	Cust No/Name LCV18734/LEE CHUN PING (LI JUNBIN)
BLK 272A SENGKANG CTRL	Reg No/Reg Date SLR4880M / 17/08/2017
#10-303	Date In/Mileage 13/12/2022/ 80972
SINGAPORE 541272	Chassis No KNAFZ411MJ5739490
Contact No Mobile: 90672077	Engine No G4FGHH679004
	Make/Model KIA/CERATO K3 1.6 A SX SR
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	13/12/2022/ 10:26	LER	972 / Mars Ler	15118
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
Z TEXT					
ACCIDENT ON 11/12/2022 ALONG TRAFFIC JUNCTION HOUGANG AVE 10					
OWNER CLAIMING THIRD PARTY					
REQUIRED REPLACEMENT CAR					
TP # GBB5786Z TP INS: LONPAC					
M SUNDRY					
C&C BADGE					50.00
M SUNDRY					
TO APPLY SEALANT KIT ON NEW PANEL					240.00
M SUNDRY					
TO APPLY ANTI-CORROSION ON ACCIDENT AFFECTED AREAS					200.00
E PNT88000					
REAR NUMBER PLATE WITH CASING					50.00
E PNT88000					
REAR REVERSE CAMERA LENS					350.00
E PNT88000					
TO CHECK AND TEST REVERSE SENSOR					100.00
E PNT88000					
TO TRANSFER TRUNK LID COMPONENT AND MECHANISM PARTS					640.00
E PNT88000					
TO REMOVE AND REINSTALL TRIMMING AND CAPERTING TO GIVE WAY ACCESS					640.00
REPAIR ON REAR ACCIDENT AFFECTED AREAS					
E PNT88000					
TO REPLACE REAR BODY KIT					640.00
E PNT88000					
TO REPLACE TRUNK LID PNL, REAR BUMPER, REAR BEAM, ETC					3840.00
-TO CUT & REWELD REAR END PANEL					
STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS					
E PNT98000					
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS					3850.00
A 10028901					
TO CONDUCT DIAGNOSTIC CHECK BY KDS AND CLEAR TROUBLE CODE					280.00
A 90000001					
					100.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lee Chun Ping (li Junbin)	Cust No/Name LCV18734/LEE CHUN PING (LI JUNBIN)
BLK 272A SENGKANG CTRL	Reg No/Reg Date SLR4880M / 17/08/2017
#10-303	Date In/Mileage 13/12/2022/ 80972
SINGAPORE 541272	Chassis No KNAFZ411MJ5739490
Contact No Mobile: 90672077	Engine No G4FGHH679004
	Make/Model KIA/CERATO K3 1.6 A SX SR
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	13/12/2022/ 10:26	LER	972 / Mars Ler	15118
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
CHECK WIRING & ELECTRICAL SYSTEM					50.00
M SUNDRY					
SUNDRIES					
M TRUNK LID PANEL ASSY	10/dec	1.00	1365.00	00.00	1365.00
M EMBLEM-CERATO	her	1.00	31.00	00.00	31.00
M EMBLEM K3	her	1.00	15.00	00.00	15.00
M LATCH ASSY-TRUNK LID	11	1.00	112.00	00.00	112.00
M W/STRIP-TRUNK LID OPNG	11	1.00	100.00	00.00	100.00
M COVER-RR BUMPER	10/dec	1.00	688.00	00.00	688.00
M COVER-RR BUMPER,CTR	torn	1.00	315.00	00.00	315.00
M COVER-RR BPR UNDER	her	1.00	42.00	00.00	42.00
M ULTRASONIC SENSOR ASSY-P.A.S	Su	4.00	177.00	00.00	708.00
M WIRING HARNESS-BWS EXT	11	1.00	216.00	00.00	216.00
M CLIP	her	10.00	2.00	00.00	20.00
M BRACKET-RR BUMPER SIDE MTG,LH	11	1.00	29.00	00.00	29.00
M BRACKET-RR BUMPER SIDE MTG,RH	11	1.00	29.00	00.00	29.00
M BEAM-RR BUMPER	cre	1.00	318.00	00.00	318.00
M BRACKET-RR BEAM LWR MTG	11	2.00	5.00	00.00	10.00
M BRACKET-RR BEAM LWR,CTR	11	1.00	5.00	00.00	5.00
M BRACKET-RR RAIL UPR MTG,LH	11	1.00	3.00	00.00	3.00
M BRACKET-RR RAIL UPR MTG,RH	11	1.00	3.00	00.00	3.00
M STAY-RR BUMPER LH	her	1.00	120.00	00.00	120.00
M STAY-RR BUMPER RH	her	1.00	120.00	00.00	120.00
M BACK PANEL ASSY	R	1.00	324.00	00.00	324.00
M BODY KIT	Torn	1.00	1800.00	00.00	1800.00
SURVEYOR NAME: <u>Mars Ler</u>					
SURVEYOR SIGNATURE: <u>[Signature]</u>					
DATE: <u>21/12/22 10am</u>					
REMARKS: <u>not aligned</u>					
<u>Whipps later party - 6 days</u>					
Confirm & accepted by					
Authorized signatory and company stamp					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed as it is subject to final approval from Insurance Company

Acknowledged by Rep **Nett** 17,403.00
 7% GST on: 17403.00 1218.21
 Date:
 Total Payable 18,621.21

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.