

CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre



330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
Lee Chun Ping (li Junbin)	Cust No/Name	LCV18734/LEE CHUN PING (LI JUNBIN)			
the chair this (th canbin)	Reg No/Reg Date	SLR4880M / 17/08/201			
BLK 272A SENGKANG CTRL	Date In/Mileage	23/12/2022/ 81605			
#10-303	Chassis No	KNAFZ411MJ5739490			
SINGAPORE 541272	Engine No	G4FGHH679004			
Contact No Mobile: 90672077	Make/Model	KIA/CERATO K3 1.6 A SX SR			
27/12/	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK			

Account No	Terms	Date/Time Pr	inted	CSE	Operator		WIP No	
СТР00080	Cash	29/12/2022/	14:55	LER	972 / Mars Ler		15118	
		Description	of Good	s / Service	s	Qty	Unit Price Disc%	Amount
OWNER CL REQUIRED	AIMING T REPLACE	2/2022 ALONG HIRD PARTY MEMT CAR (CHA TP INS: LON	N'S)	JUNCTION	HOUGANG AVE 10			
M SUNDRY C&C BADO		II INS. LON	1710					50.00
M SUNDRY		KIT ON NEW P	ANFI					80.00
M SUNDRY		RROSION ON AC		VEECTED	ADEAS			100.00
E PNT88000		E WITH CASING				14/6	2)	50.00
E PNT88000			A STATE OF THE PROPERTY OF THE PARTY OF THE	0)4	ll li li e	176	ラ	100.00
E PNT88000		T REVERSE SEN K LID COMPONE		MECHANIEM	DADTE			320.00
E PNT88000 TO REMOV	/E AND RE		ING AND	CAPERTIN	G TO GIVE WAY ACCESS	5		320.00
E PNT88000	ACE REAR							320.00
E PNT88000 TO REPLA	ACE TRUNK	LID PNL,REAR	BUMPER	,REAR BEA	M,ETC			1920.00
STRAIGH E PNT98000	TEN, REFOR	M,ALIGN ON RE						1925.0
A 10028901		N REAR ACCIDE OSTIC CHECK B						280.0
A 90000001		LECTRICAL SYS		NO CLEAR	TROUBLE CODE			80.0
M SUNDRY	TIVING & E	LEGIKICAL 313	TEM					30.0

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre



330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
Lee Chun Ping (li Junbin)	Cust No/Name	LCV18734/LEE CHUN PING (LI JUNBIN)		
	Reg No/Reg Date	SLR4880M / 17/08/201		
BLK 272A SENGKANG CTRL	Date In/Mileage	23/12/2022/ 81605		
#10-303 SINGAPORE 541272	Chassis No	KNAFZ411MJ5739490		
31NGAPORE 341272	Engine No	G4FGHH679004		
Contact No Mobile: 90672077	Make/Model	KIA/CERATO K3 1.6 A SX SR		
27/12/	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK		

Account No	Terms	Date/Time Pr	at y to an take the same	CSE	Operator		WIP No		
TP00080	Cash	29/12/2022/	14:55	LER	972 / Mars	Ler	15118		
	CALL N	Description	of Goods	/ Services	The second	Qt	y Unit Price	Disc%	Amount
SUNDRIES TRUNK LIC EMBLEM-CE EMBLEM K3 COVER-RR COVER-RR COVER-RR CLIP BEAM-RR STAY-RR STAY-RR BODY KIT	BUMPER BUMPER, BUMPER, BPR UNDI BUMPER BUMPER LI	CTR ER	haven (SIL		1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0	0 31.00 0 15.00 0 688.00 0 315.00 0 42.00 0 2.00 0 318.00 0 120.00	00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00	1365.0 31.0 15.0 688.0 315.0 42.0 20.0 318.0 120.0 1800.0
		and the second s		941		all.	3		
Confirm & a	ccepted l	ру							
						7% GS1		tt 00	10,409. 728.
Finaliz	ation						Total Payab	1e	11,137.
		y and company	ctamn						

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.