



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7134K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER FRT COVER	DEFORMED	1,052.20	1,052.20
1	LAMP ASSY-HEAD LH	SERVICEABLE	1,388.00	-
1	PANEL-FENDER LH	TO REPAIR SEE LABOUR	663.00	-
1	BRACKET-FR BUMPER SIDE LH	SERVICEABLE	44.80	-
	LESS 20% DISCOUNT		-629.60	-210.44
			2,518.40	841.76
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF PANEL-FENDER LH.		600.00	560.00
	SPRAYPAINT CHARGE.		600.00	500.00
	TUFF COAT ON AFFECTED PARTS.		50.00	40.00
	CHECK ALL LIGHTING.	NOT NECESSARY	50.00	-
			1,300.00	1,100.00
	GRAND TOTAL		3,818.40	1,941.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,550.00

Report Ref No. NS/INC22012444/Nwp3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.