2/3/23, 1:24 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI22012451/KQP3Q2

03/02/2023 Date:

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MN000212 **Claimant Vehicle**

SHC5295Y Insured Vehicle No: SLM7624T No:

Date of Loss: 25/11/2022 Nature of Claim: ΤP Claim No: M2206741

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5295Y**

TOYOTA PRIUS, 1.5 (A) Make & Model: 2ZR2H17497 Engine No:

Reg. Date: 13/11/2020 (Man. Year: 2020) Chassis No: JTDKB3FU403092677

Colour: Metallic Pearl White/Red Odometer: 268947 km

Engine Capacity: 1798 cc Market Value/New Car

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Nο Pre-accident Condition:

CONDITION OF TYRES

195/65 R15 Front Tyre Size: 195/65 R15 Rear Tyre Size: Front Left Side: Grenlander 9 mm Rear Left Side: Wanli 8 mm Front Right Side: Grenlander 9 mm Rear Right Side: Wanli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,619.85	523.65	3,096.20	85.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	480.00	4,620.00	90.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S	\$) 8,719.85	1,003.65	7,716.20	88.49
+ GST 8.00/8.00% (S	\$) 697.59	80.29	617.30	88.49
Nett Amount (S	\$) 9,417.44	1,083.94	8,333.50	88.49

INSPECTION

Date of Assignment: 14/12/2022

Trans-cab Auto Services Pte Ltd Date Inspected: 12/12/2022 Inspected At: No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG SHIAU CHAN Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

2/3/23, 1:24 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Feb 2023)

Parts: 144 TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC5295Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

Condition

Donairor's

Amount

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts No. Oty. Part No. Particulars

NO.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, REAR BUMPER	Bent	485.60 FL	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
3	1		*GUARD ,REAR BUMPER CENTER	Serviceable	374.50 FL	*- FL
4	1		*SEAL ,REAR BUMPER SIDE ,RH	Serviceable	118.30 FL	*- FL
5	1		*RETAINER ,REAR BUMPER SIDE ,RH	Distorted	132.60 FL	*132.60 FL
6	1		*COVER ,REAR BUMPER ,LOWER	Serviceable	22.00 FL	*- FL
7	1		*COVER ,DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
8	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
9	1		*REFLECTOR ASSY ,REFLEX ,RH	Serviceable	39.00 FL	*- FL
10	1		*COVER ,FLOOR UNDER NO.2 (RH)	Serviceable	241.90 FL	*- FL
11	1		*COVER ,FLOOR UNDER NO.1 (LH)	Serviceable	175.10 FL	*- FL
12	1		*COVER ,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
13	1		*LENS & BODY ,REAR COMBINATION LAMP RH (UPPER)	Serviceable	339.60 FL	*- FL
14	1		*LENS & BODY ,REAR COMBINATION LAMP,NO.2 (LOWER)	Serviceable	261.00 FL	*- FL
15	1		*COVER ,REAR COMBINATION LAMP ,RH	Serviceable	69.90 FL	*- FL
16	1		*REAR BUMPER SIDE CLIP	Necessary	60.00 FS	*60.00 FS
17	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
18	1		*SET REAR BUMPER CLIP	Not Necessary	85.00 FS	*- FS
19	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.	,		
				Sub Total (S\$)	4,519.80	678.20
			- List Item Discount on L Items	25.00/25.00% (S\$)	899.95	154.55
				Total Parts (S\$)	3,619.85	523.65
				,		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,600.00	200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	220.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
	Gross Labou	r Cost (S\$)	5,100.00	480.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >