

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22012454/KYA3Q2**Date:** 30/05/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0004693_02
Claimant Vehicle No : SCA6088S **Insured Vehicle No :** SNJ8K
 Date of Loss: 09/12/2022 Nature of Claim: TP Claim No: MFL2022D0011593

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCA6088S**
 Make & Model: MERCEDES-BENZ C180, 1.8 CGI (A) Engine No: 27182030041377
 Reg. Date: 14/06/2010 (Man. Year: 2010) Chassis No: WDD2040492A373992
 Colour: Metallic Grey Odometer: 136237 km
 Engine Capacity: 1796 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
 Front Left Side: Goodyear 8 mm Rear Left Side: Goodyear 8 mm
 Front Right Side: Goodyear 8 mm Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,279.00	18,087.90	14,191.10	43.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,650.00	5,240.00	2,410.00	31.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,929.00	23,327.90	16,601.10	41.58
Approved Total (Overridden) (S\$)		18,300.00		
Nett Amount (S\$)	39,929.00	18,300.00	21,629.00	54.17
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 13/12/2022
 Date Inspected: 14/12/2022 Inspected At: Poon Siang Seow (HQ)
 160 Sin Ming Drive, #05-13 Sin Ming AutoCity
 Singapore 575722
 Estimated Period of Repair: 21.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2023)
Parts:	143	MERCEDES-BENZ C180 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCA6088S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FORNT BONNET	Bent	2,130.00 F	*2,130.00 FL
2	2		*FORNT BONNET HINGE	*Check	240.00 F	*- FL
3	1		*FORNT BONNET LOGO	Necessary	55.00 F	*55.00 FL
4	1		*FORNT BONNET HOOK	O/S Distorted	100.00 F	*50.00 FL
5	2		*FORNT BONNET DAMPER	*Check	320.00 F	*- FL
6	1		*FORNT BONNET COVER GARISH	*Check	180.00 F	*- FL
7	1		*FORNT BONNET LOCK	O/S Bent	460.00 F	*230.00 FL
8	1		*FRONT BUMPER	Buckled	1,233.00 F	*1,233.00 FL
9	1		*FRONT BUMPER INNER PART	Cracked	108.00 F	*108.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Bent	688.00 F	*688.00 FL
11	2		*FRONT BUMPER BRACKET	*Check	240.00 F	*- FL
12	1		*FRONT BUMPER SPONGE	Cracked	128.00 F	*128.00 FL
13	2		*FRONT BUMPER MOULDING	Necessary	264.00 F	*264.00 FL
14	2		*FRONT BUMPER FOG LAMP	O/S *Check / N/S Serviceable	1,160.00 F	*- FL
15	1		*FRONT BUMPER TOWING COVER	Missing	45.00 F	*45.00 FL
16	1		*FRONT BUMPER LOWER GRILLE	Distorted	103.00 F	*103.00 FL
17	1		*FRONT GRILLE	Cracked	850.00 F	*850.00 FL
18	1		*FRONT GRILLE TOP COVER GARISH	Cracked	180.00 F	*180.00 FL
19	3		*FRONT SUPPORT PANEL	*Check	950.00 F	*- FL
20	1		*RADIATOR	*Check	1,080.00 F	*- FL
21	1		*AIR CONDENSER	*Check	980.00 F	*- FL
22	1		*FAN AND MOTOR COWING	*Check	890.00 F	*- FL
23	1		*AIR FILTER OUTLET GARISH	*Check	203.00 F	*- FL
24	1		*RADIATOR SPARE TANK	*Check	102.00 F	*- FL
25	1		*TAIL BOOT COVER	Bent	1,772.00 F	*1,772.00 FL
26	1		*TAIL BOOT INNER LOCK	Jammed	314.00 F	*314.00 FL
27	2		*TAIL BOOT COVER HINGE	Bent	240.00 F	*240.00 FL
28	2		*TAIL BOOT HINGE COVER GARISH	*Check	160.00 F	*- FL
29	1		*TAIL BOOT LOGO	Necessary	51.00 F	*51.00 FL
30	1		*TAIL BOOT BADGE C180	Necessary	68.00 F	*68.00 FL
31	1		*TAIL BOOT BADGE DGI	Necessary	68.00 F	*68.00 FL
32	1		*TAIL BOOT OUTER HANDLE	Warped	319.00 F	*319.00 FL
33	1		*TAIL BOOT OUTER LOCK	*Check	201.00 F	*- FL
34	2		*TAIL BOOT NUMBER PLATE LAMP	*Check	60.00 F	*- FL
35	1		*TAIL BOOT GARISH COVER	Deformed	320.00 F	*320.00 FL
36	1		*TAIL BOOT RUBBER (50%)	Distorted / Dented	156.00 FS	*78.00 FS
37	1		*TAIL LAMP LEFT	Cracked	793.00 F	*793.00 FL
38	1		*TAIL LAMP RIGHT	Broken	793.00 F	*793.00 FL
39	1		*TAIL LAMP HOUSING RIGHT	Bent	340.00 F	*340.00 FL
40	1		*REAR PANEL	Bent	1,358.00 F	*1,358.00 FL
41	1		*REAR PANEL TOP GARISH	Distorted	240.00 F	*240.00 FL
42	1		*REAR BUMPER	Bent	1,595.00 F	*1,595.00 FL
43	1		*REAR BUMPER INNER PART	Bent	108.00 F	*108.00 FL
44	1		*REAR BUMPER SENSOR	Dented / Shorted	350.00 F	*350.00 FL
45	1		*REAR BUMPER REINFORCEMENT	Bent	738.00 F	*738.00 FL
46	2		*REAR BUMPER SIDE MOULDING	Necessary	290.00 F	*290.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR BUMPER CENTRE MOULDING	Necessary	205.00 F	*205.00 FL
48	1		*REAR TYRES SPARE BOARD	*Check	350.00 F	*- FL
49	1		*REAR SPARE TYRE PANEL GARISH	*Check	550.00 F	*- FL
50	2		*REAR CHASSIS MEMBER	*Check	1,796.00 F	*- FL
51	1		*REAR FENDER RIGHT	Buckled	1,205.00 F	*1,205.00 FL
52	2		*REAR FENDER INNER SIDE COVER	*Check	1,200.00 F	*- FL
53	4		*SEAT BELT	Jammed	2,080.00 F	*2,080.00 FL
54	2		*HEAD REST	Activated	700.00 F	*700.00 FL
55	1		*RELAY SENSOR	*Check	280.00 F	*- FL
56	1		*REAR EXHAUST BOX	*Check	890.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	32,279.00	20,089.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	2,001.10
Total Parts (\$)	32,279.00	18,087.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST PROOFING	New	100.00	100.00
2	PANEL BEATING	New	3,800.00	2,600.00
3	SPRAY PAINTING	New	2,500.00	2,200.00
4	TO REMOVE AND REFIT REAR W/S GLASS AND CUSHION	New	500.00	240.00
5	AIR CON GAS AND CHECK	New	550.00	100.00
6	TOWING (*Check)	New	200.00	0.00
Gross Labour Cost (S\$)			7,650.00	5,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >