

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012458/AQP3E2
Date: 13/03/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00014112207
Claimant Vehicle No :	PC2887P	Insured Vehicle No :	CB7451P
Date of Loss:	08/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D208864/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC2887P	Engine No:	1KD2428175
Make & Model:	TOYOTA HIACE, 3.0 COMMUTER GL (A)	Chassis No:	KDH2230020763
Reg. Date:	14/10/2014 (Man. Year: 2014)	Odometer:	357095 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	DURATURN 6 mm	Rear Left Side:	DURATURN 6 mm
Front Right Side:	DURATURN 6 mm	Rear Right Side:	DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,339.77	5,842.20	3,497.57	37.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	2,070.00	1,760.00	45.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,169.77	7,912.20	5,257.57	39.92
Approved Total (Overridden) (S\$)		6,300.00		
Nett Amount (S\$)	13,169.77	6,300.00	6,869.77	52.16

INSPECTION

Date of Assignment:	13/12/2022	Automobile Hub Enterprise
Date Inspected:	13/12/2022 Inspected At:	1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT
Estimated Period of Repair:	6.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Mar 2023)	
Parts:	N/A	TOYOTA HIACE 3.0 COMMUTER GL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC2887P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP	Not Necessary	158.20 FL	*- FL
2	1		*REAR BUMPER	Deformed	522.40 FL	*522.40 FL
3	2		*REAR BUMPER SIDE HOLDER	Necessary	110.20 FL	*110.20 FL
4	3		*REAR BUMPER LOWER BRACKET	Bent	65.40 FL	*65.40 FL
5	1		*REAR END PANEL OUTER	Dented	698.40 FL	*698.40 FL
6	1		*REAR END PANEL INNER	Repair	897.50 FL	*- FL
7	1		*REAR END PANEL TOP GARNISH	Not Necessary	259.30 FL	*- FL
8	2		*TAILLAMP	N/S Cut / O/S Cracked	781.00 FL	*781.00 FL
9	2		*TAILLAMP LOWER APRON	Not Necessary	334.40 FL	*- FL
10	1		*TAILGATE	Dented	1,855.00 FL	*1,855.00 FL
11	1		*TAILGATE LOCK	Damaged	398.40 FL	*398.40 FL
12	1		*TAILGATE LOCK ACTUATOR	Not Necessary	395.30 FL	*- FL
13	1		*TAILGATE WEATHERSTRIPE	Cut	395.10 FL	*395.10 FL
14	1		*TAILGATE OUTER CHROME MOULDING	Deformed	364.90 FL	*364.90 FL
15	1		*TAILGATE INNER TRIM BOARD	Cracked	481.30 FL	*481.30 FL
16	1		*TAILGATE GLASS	Shattered	1,254.20 FL	*1,254.20 FL
17	1		*TAILGATE GLASS MOULDING	Necessary	140.40 FL	*140.40 FL
18	1		*TAILGATE WIPER MOTOR	Not Necessary	430.10 FL	*- FL
19	1		*TOYOTA LOGO	Necessary	75.20 FL	*75.20 FL
20	1		*HIACE WORDING	Necessary	73.60 FL	*73.60 FL
21	1		*GL EMBLEM	Necessary	54.10 FL	*54.10 FL
22	1		*SPARE TYRE CARRIAGE	Not Necessary	388.90 FL	*- FL
23	1		*SPARE TYRE LOCK SCREW	Not Necessary	121.20 FL	*- FL
24	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
25	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
26	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
27	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
28	1		*TAILGATE OUTER CHROME MOULDING CLIPS	Necessary	20.00 FS	*20.00 FS
29	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
30	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
31	1		*70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
32	1		*REAR CAMERA	Not Necessary	380.00 FS	*- FS
33	1		*REAR VIDEO RECORDER	Not Necessary	580.00 FS	*- FS
34	1		*SCHOOL CHILDREN WARNING SIGN	Damaged	380.00 FS	*150.00 FS
35	1		*TAILGATE WIPER ARM	Not Necessary	65.20 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,919.70	7,659.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,579.93	1,817.40
Total Parts (\$\$)	9,339.77	5,842.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	800.00
2	SPRAY PAINTING	New	1,400.00	800.00
3	WIRING	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	40.00
6	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
7	TO REMOVE TAILGATE GLASS	New	180.00	120.00
8	TO VACUUM GLASS SHARDS & CLEAN INTERIOR	New	100.00	60.00
9	TO REMOVE REAR CAMERA	New	100.00	50.00
10	TO REMOVE REAR VIDEO RECORDER	New	100.00	50.00
Gross Labour Cost (\$)			3,830.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >