

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

Tp China.

Xiao Chen.

Page No. 1

Vehicle No. PC2887P

TOYOTA HIACE COMMUTER

KDH2230020763

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	REAR NUMBER PLATE LAMP @79.10 <i>not new</i>		158.20	X
2	REAR BUMPER <i>Deformed</i>		522.40	✓
3	REAR BUMPER SIDE HOLDER @55.10 <i>new</i>		110.20	✓
4	REAR BUMPER LOWER BRACKET @21.80 <i>Bent</i>		65.40	✓
5	REAR END PANEL OUTER <i>Dented</i>		698.40	✓
6	REAR END PANEL INNER <i>Repis</i>		897.50	X.
7	REAR END PANEL TOP GARNISH <i>not new</i>		259.30	X
8	TAILLAMP @390.50 <i>Left out, Rth cracked</i>		781.00	✓
9	TAILLAMP LOWER APRON @167.20 <i>not new</i>		334.40	X.
10	TAILGATE <i>Dented</i>		1855.00	✓
11	TAILGATE LOCK <i>Damaged</i>		398.40	✓
12	TAILGATE LOCK ACTUATOR <i>not new</i>		395.30	X.
13	TAILGATE WEATHERSTRIPE <i>hit</i>		395.10	✓
14	TAILGATE OUTER CHROME MOULDING <i>peeled</i>		364.90	✓
15	TAILGATE INNER TRIM BOARD <i>cracked</i>		481.30	✓
16	TAILGATE GLASS <i>shattered</i>		1254.20	✓
17	TAILGATE GLASS MOULDING <i>new</i>		140.40	✓
18	TAILGATE WIPER MOTOR <i>not new</i>		430.10	X
19	TAILGATE WIPER ARM <i>not new</i>		65.20	X
20	TOYOTA LOGO		75.20	✓
21	HIACE WORDING <i>new</i>		73.60	✓
22	GL EMBLEM		54.10	✓
23	SPARE TYRE CARRIAGE <i>new</i>		388.90	X
24	SPARE TYRE LOCK SCREW <i>new</i>		121.20	X.
			10161.50	
less 25%			2540.38	25%
			7621.13	
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE <i>Bent</i>		30.00	✓
2	REAR NBUMPER CLIPS <i>new</i>		30.00	✓
3	REAR END PANEL SEALANT <i>new</i>		60.00	✓
4	REAR END PANEL TOP GARNISH CLIPS <i>not new</i>		20.00	X
5	TAILGATE OUTER CHROME MOULDING CLIPS <i>new</i>		20.00	✓
6	TAILGATE INNER TRIM BOARD CLIPS <i>new</i>		30.00	✓
7	TAILGATE GLASS SEALANT <i>new</i>		60.00	✓
8	70KM/H STICKER <i>new</i>		10.00	✓
9	RAER CAMERA <i>not new</i>		380.00	X
10	REAR VIDEO RECORDER <i>not new</i>		580.00	X
11	SCHOOL CHILDREN WARNING SIGN <i>Damaged</i>		380.00	150.
Total Parts			1600.00	

7269.60

5452.20

390

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

Page No. 2

Vehicle No. PC2887P

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	PANEL BEATING	1400.00	800
2	SPRAY PAINTING	1400.00	800
3	WIRING	100.00	30
4	TO APPLY TUFF COAT	150.00	60
5	TO REMOVE UPHOLSTERY	150.00	40
6	TO TRANSFER TAILGATE FITTINGS	150.00	80
7	TO REMOVE TAILGATE GLASS	180.00	120
8	TO VACCUM GLASS SHARDS & CLEAN INTERIOR	100.00	60
9	TO REMOVE REAR CAMERA	100.00	50
10	TO REMOVE REAR VIDEO RECORDER	100.00	50
	Labour Total :	3830.00	2070
TOTAL (PARTS & LABOUR):		13051.13	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 7912.20

h/s: 6.3K.

06 Days.