

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012460/RVP3Q2**Date:** 05/06/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00087202200

**Claimant Vehicle
No :** SND78P**Insured Vehicle
No :** YQ2951G

Date of Loss: 10/12/2022

Nature of Claim: TP

Claim
No: SNM22D208939/C02/LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SND78P**

Make & Model: VOLKSWAGEN SHARAN, 2.0 TSI (A)

Engine No: DED036063

Reg. Date: 26/03/2021 (Man. Year: 2020)

Chassis No: WVVZZZ7NZMV002696

Colour: White

Odometer: 35441 km

Engine Capacity: 1984 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,366.07	13,726.31	6,639.76	32.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,685.00	8,690.00	3,995.00	31.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	33,051.07	22,416.31	10,634.76	32.18
+ GST 8.00/8.00% (S\$)	2,644.09	1,793.30	850.79	32.18
Nett Amount (S\$)	35,695.16	24,209.61	11,485.55	32.18

INSPECTION

Date of Assignment: 13/12/2022

Date Inspected: 14/12/2022 Inspected At:

Volkswagen Centre Singapore (Tuas)
17 TUAS AVENUE
Singapore 639176

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Please be informed that TP convert to OD claim

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2023)
Parts:	M1-MPV	VOLKSWAGEN SHARAN 2.0 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND78P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WATER DEFLECTOR SATIN BLA RHS WIPER COWLING	Cracked	103.86 FS	*103.86 FS
2	1		*HOOD	Bent	1,796.13 FS	*1,796.13 FS
3	1		*JOUNCE BUMPER BONNET STOP BUFFER (2 PCS)	Necessary (1 PCS ONLY)	47.66 FS	*23.83 FS
4	1		*FLAP HINGE LH	Bent	194.26 FS	*194.26 FS
5	1		*FLAP HINGE RH	Bent	194.26 FS	*194.26 FS
6	1		*HOOK BONNET LATCH	Bent	105.83 FS	*105.83 FS
7	3		*BOLT HEX HD	Necessary	12.00 FS	*12.00 FS
8	1		*HOOD LATCH LOWER PORTION BONNET LOCK	Bent	160.93 FS	*160.93 FS
9	1		*HOOD SILENCER BONNET INSULATOR	Deformed	316.21 FS	*316.21 FS
10	1		*COVER FOR BUMPER PRIMED	Deformed	2,212.59 FS	*2,212.59 FS
11	1		*FRONT SPOILER SATIN BLACK	Not Necessary	180.73 FS	*- FS
12	1		*CAP PRIMED TOWING COVER	Not Necessary	71.34 FS	*- FS
13	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Necessary	44.68 FS	*44.68 FS
14	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Necessary	44.68 FS	*44.68 FS
15	1		*SUPPORT PART RHS NOZZLE CYLINDER BRACKET	Not Necessary	36.70 FS	*- FS
16	1		*GUIDE PIECE BUMPER CTR BRACKET	Cracked	160.06 FS	*160.06 FS
17	1		*BUMPER BRACKET REINFORCEMENT	Not Necessary	944.96 FS	*- FS
18	1		*PRESSURE CYLINDER RHS NOZZLE CYLINDER	Not Necessary	211.03 FS	*- FS
19	1		*JET CARRIER WITH JET RHS NOZZLE	Not Necessary	48.98 FS	*- FS
20	1		*CAP PRIMED RHS NOZZLE COVER	Missing	70.36 FS	*70.36 FS
21	1		*ELBOW L-JOINT	Not Necessary	18.44 FS	*- FS
22	1		*DISTRIBUTOR PIECE T-JOINT	Not Necessary	20.77 FS	*- FS
23	1		*HOSE IN COILS OF 5M ORDE	Not Necessary	34.73 FS	*- FS
24	6		*CLIP	Necessary	10.20 FS	*10.20 FS
25	1		*SENSOR PRIMED PARKING SENSOR (SIDE)	*Check	190.18 FS	*- FS
26	1		*SEAL RING SATIN BLACK	Not Necessary	0.87 FS	*- FS
27	1		*SENSOR PRIMED	*Check	190.18 FS	*- FS
28	1		*SEAL RING SATIN BLACK	Not Necessary	0.87 FS	*- FS
29	1		*RADIATOR GRILLE SATIN BLA	Cracked	739.52 FS	*739.52 FS
30	1		*VW SIGN BLACK HIGH GLASS	Missing	141.79 FS	*141.79 FS
31	1		*GRILLE SATIN BLACK BUMPER CTR LOWER GRILLE	Not Necessary	251.12 FS	*- FS
32	1		*DECORATIVE MOULDING BRIGH BUMPER CTR LOWER GRILLE CHROME	Not Necessary	239.35 FS	*- FS
33	1		*COOLING AIR GRILL SATIN B RHS FOG LAMP GRILLE	Scratched	189.91 FS	*189.91 FS
34	1		*PROTECTIVE STRIP BRIGHT C RHS FOG LAMP GRILLE CHROME	Necessary	120.75 FS	*120.75 FS
35	1		*HEADLAMPS FOR CURVE LIGHT LH	Not Necessary	2,669.12 FS	*- FS
36	1		*HEADLAMPS FOR CURVE LIGHT RH	Broken	2,669.12 FS	*2,669.12 FS
37	1		*GAS DISCHA	Necessary	634.25 FS	*634.25 FS
38	1		*HALOGEN BULB LONGLIFE	Cracked	40.84 FS	*40.84 FS
39	1		*BULB YELLOW GLASS LONGLI	Cracked	9.63 FS	*9.63 FS
40	1		*CONTROL UNIT FOR CORNERIN	Missing	695.74 FS	*695.74 FS
41	1		*BALLAST FOR GAS DISCHARGE	Missing	946.95 FS	*946.95 FS
42	1		*POWER MODULE FOR DAY DRIV	Missing	469.86 FS	*469.86 FS
43	1		*FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING	Cut	21.54 FS	*21.54 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	2		*HEXAGON SOCKET HEAD BOLT	Necessary	8.44 FS	*8.44 FS
45	1		*HALOGEN FOG LIGHTS WITH S RH	Cracked	372.13 FS	*372.13 FS
46	1		*LOCK CARRIER WITH MOUNTIN	*Check	1,247.85 FS	*- FS
47	1		*SUPPORT FOR LOCK CARRIER	*Check	132.81 FS	*- FS
48	1		*CROSS SUPPORT RHS H/LAMP TOP PANEL	Bent	66.53 FS	*66.53 FS
49	2		*COOLANT 1B	*Check	45.90 FS	*- FS
50	1		*HORN	Cracked	151.73 FS	*151.73 FS
51	1		*HALTER FUER SIGNALHORN HORN BRACKET	Bent	37.20 FS	*37.20 FS
52	1		*FENDER RH	Buckled	714.05 FS	*714.05 FS
53	1		*CROSS SUPPORT RHS FENDER BRACKET	Bent	53.04 FS	*53.04 FS
54	1		*WHEELHOUSE LINER RHS FENDER LINER	Cracked	173.61 FS	*173.61 FS
55	6		*EXPANDING NUT	Necessary	11.88 FS	*11.88 FS
56	6		*HEXAGON SOCKET HEAD PANEL	Necessary	7.92 FS	*7.92 FS
57	1		*FRT NUMBER PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 20,366.07 13,726.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING ASSISTANCE -AWP (*Check)	New	195.00	0.00
2	LABOUR	New	5,040.00	2,520.00
3	SPRAY PAINT	New	4,800.00	4,000.00
4	SPRAY RHS FRT RIM	New	400.00	400.00
5	COATING	New	500.00	500.00
6	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
7	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
8	B&P LEAKED CHECK ,VACUUM & REGAS (*Check)	New	420.00	0.00
9	A/C GAS (*Check)	New	60.00	0.00
10	B&P WHEEL ALIGNMENT	New	360.00	360.00
11	R&R RIM & BALANCE	New	50.00	50.00
12	TO ALIGN HEADLIGHT	New	100.00	100.00
Gross Labour Cost (S\$)			12,685.00	8,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >