

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012462/AVP3Q2**Date:** 22/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00045772201	
Claimant Vehicle No :	SNC3400C	Insured Vehicle No :	GBL1911C	
Date of Loss:	08/12/2022	Nature of Claim:	TP	Claim No: SNM22D208935/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC3400C		Engine No:	L15B6023398
Make & Model:	HONDA SHUTTLE, 1.5 G CVT SENSING (A)		Chassis No:	GK82102905
Reg. Date:	13/10/2021 (Man. Year: 2019)		Odometer:	43463 km
Colour:	Silver			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,461.24	5,214.16	2,247.08	30.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	2,000.00	530.00	20.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,991.24	7,214.16	2,777.08	27.80
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	9,991.24	5,700.00	4,291.24	42.95
+ GST 7.00/7.00% (S\$)	699.39	399.00	300.39	42.95
Nett Amount (S\$)	10,690.63	6,099.00	4,591.63	42.95

INSPECTION

Date of Assignment: 21/12/2022

Date Inspected: 13/12/2022 Inspected At:

N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Dec 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT SENSING (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC3400C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,150.40 FL	*985.00 FL
2	1		*REAR BUMPER CENTER CHROME MOULDING	Cracked	148.20 FL	*148.20 FL
3	2		*REAR BUMPER INNER SPONGE L/R	Cracked	197.00 FL	*197.00 FL
4	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	98.40 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	56.80 FL	*- FL
6	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	29.50 FL	*- FL
7	1		*REAR END PANEL	Dented	560.20 FL	*560.20 FL
8	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	50.20 FL	*- FL
9	1		*REAR END PANEL INNER TOP GARNISH	Deformed	155.40 FL	*155.40 FL
10	1		*REAR TAILGATE	Distorted	1,293.40 FL	*1,293.40 FL
11	1		*REAR TAILGATE LOGO EMBLEM	Necessary	39.40 FL	*39.40 FL
12	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	59.80 FL	*59.80 FL
13	2		*REAR TAILGATE HINGES L/R	Not Necessary	118.80 FL	*- FL
14	1		*REAR TAILGATE INNER PULL HANDLE	Deformed	29.40 FL	*29.40 FL
15	2		*REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	Not Necessary	18.80 FL	*- FL
16	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	280.40 FL	*280.40 FL
17	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	49.20 FL	*- FL
18	1		*REAR TAILGATE MECHANISM LOCK	Damaged	228.40 FL	*228.40 FL
19	2		*REAR TAILGATE NUMBER PLATE LAMP L/R	Not Necessary	319.60 FL	*- FL
20	1		*REAR TAILGATE OUTER GARNISH WITH CHROME	Cracked	410.90 FL	*410.90 FL
21	2		*REAR TAILGATE REFLECTOR L/R	Cracked	841.80 FL	*841.80 FL
22	1		*REAR TAILGATE WEATHERSTRIP	Cut	168.20 FL	*168.20 FL
23	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	149.30 FL	*149.30 FL
24	1		*REAR TAILLAMP L/R	N/S Cut	1,041.80 FL	*520.90 FL
25	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
26	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
27	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*10.00 FS
28	1		*REAR TAILGATE CAMERA	Not Necessary	800.00 FS	*- FS
29	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
30	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
31	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
32	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
33	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
34	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	50.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,960.30	6,427.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,499.06	1,213.54
Total Parts (\$\$)	7,461.24	5,214.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
2	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	100.00	60.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
5	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
7	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
Gross Labour Cost (\$\$)			2,530.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >