

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012464/TNP3Q2**Date:** 16/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00019922203
Claimant Vehicle No :	SJS7342Z	Insured Vehicle No :	SJP9611A
Date of Loss:	08/12/2022	Nature of Claim: TP	Claim No: SNM22D208872/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS7342Z	Engine No:	CAV108852
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 L (A)	Chassis No:	WVWZZZ13ZAV410762
Reg. Date:	13/10/2009 (Man. Year: 2009)	Odometer:	295209 km
Colour:	Blue		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,463.66	6,936.33	4,527.33	39.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,090.00	1,810.00	2,280.00	55.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,553.66	8,746.33	6,807.33	43.77
Approved Total (Overridden) (S\$)		6,900.00		
(S\$)	15,553.66	6,900.00	8,653.66	55.64
+ GST 8.00/8.00% (S\$)	1,244.29	552.00	692.29	55.64
Nett Amount (S\$)	16,797.95	7,452.00	9,345.95	55.64

INSPECTION

Date of Assignment:	14/12/2022	
Date Inspected:	14/12/2022 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2023)
Parts:	144	VOLKSWAGEN SCIROCCO 1.4 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS7342Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,601.83 FL	*1,601.83 FL
2	1		*TAILGATE CENTRE EMBLEM	Necessary	68.50 FL	*68.50 FL
3	1		*TAILGATE LOCK	Jammed	167.50 FL	*167.50 FL
4	1		*TAILGATE LOCK CATCH	Not Necessary	74.30 FL	*- FL
5	1		*TAILGATE WEATHERSTRIP	Twisted	214.60 FL	*214.60 FL
6	1		*TAILGATE INNER TRIM BOARD	Cracked	286.50 FL	*286.50 FL
7	1		*TAILGATE WIPER MOTOR	Obstructed	532.10 FL	*- FL
8	1		*REAR BUMPER	Deformed	1,103.40 FL	*1,103.40 FL
9	1		*REAR BUMPER RH REFLECTOR	Not Necessary	78.90 FL	*- FL
10	1		*REAR BUMPER LH REFLECTOR	Not Necessary	78.90 FL	*- FL
11	1		*REAR BUMPER NUMBER PLATE RH LAMP	Cracked	55.70 FL	*55.70 FL
12	1		*REAR BUMPER NUMBER PLATE LH LAMP	Cracked	55.70 FL	*55.70 FL
13	1		*REAR BUMPER INNER CENTRE BRACKET	Cracked	73.20 FL	*73.20 FL
14	1		*REAR BUMPER RH SIDE RETAINER	Missing	41.20 FL	*41.20 FL
15	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	41.20 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	453.17 FL	*453.17 FL
17	1		*LH TAILLAMP	Cut	464.30 FL	*464.30 FL
18	1		*LH TAILLAMP PANEL	Not Necessary	178.20 FL	*- FL
19	1		*SET LH TAILLAMP LOCK CLIPS	Not Necessary	28.00 FL	*- FL
20	1		*RH TAILLAMP	Cut	464.30 FL	*464.30 FL
21	1		*RH TAILLAMP PANEL	Not Necessary	178.20 FL	*- FL
22	1		*SET RH TAILLAMP LOCK CLIPS	Not Necessary	28.00 FL	*- FL
23	1		*END PANEL	Bent	785.90 FL	*528.00 FL
24	1		*END PANEL GARNISH	Deformed	119.80 FL	*119.80 FL
25	1		*REAR FENDER RH INNER TRIM	Not Necessary	343.20 FL	*- FL
26	1		*REAR FENDER LH INNER TRIM	Not Necessary	343.20 FL	*- FL
27	1		*REAR SPARE TYRE PANEL TOP BOARD	Not Necessary	287.50 FL	*- FL
28	1		*REAR SPARE TYRE PANEL	Repair	874.20 FL	*- FL
29	1		*EXHAUST SILENCER	Bent	1,548.90 FL	*1,459.00 FL
30	1		*EXHAUST SILENCER GASKET	Necessary	67.00 FL	*67.00 FL
31	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	80.00 FS	*30.00 FS
32	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
33	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	60.00 FS	*30.00 FS
34	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
35	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	350.00 FS	*200.00 FS
36	1		*REAR BUMPER REVERSE CAMERA	Not Necessary	750.00 FS	*- FS
37	1		*SET END PANEL GARNISH CLIPS	Necessary	60.00 FS	*20.00 FS
38	1		*SET REAR FENDER LH INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
39	1		*SET REAR FENDER RH INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
40	1		*REAR NUMBER PLATE	Cracked	70.00 FS	*45.00 FS
41	1		*END PANEL JOINT SEALANT	Necessary	80.00 FS	*40.00 FS
42	1		*END PANEL INNER GARNISH	Not Necessary	60.00 FS	*- FS
43	1		*RH TAILLAMP PANEL JOINT SEALANT	Not Necessary	50.00 FS	*- FS
44	1		*LH TAILLAMP PANEL JOINT SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.		
Sub Total (\$\$) 12,527.40 7,658.70		

Report was unsubmitted during this print-out.		
---	--	--

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/10.00% (S\$)					1,063.74	722.37
Total Parts (S\$)					11,463.66	6,936.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGED BODYPARTS .TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,500.00	700.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	100.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	120.00	30.00
5	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS AND SEALANTS TO ASSIST REPAIR	New	200.00	120.00
6	REMOVE AND REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE	New	180.00	60.00
7	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	30.00
8	REMOVE AND REPLACE REAR INNER TRIM ,GARNISH AND BOARDS TO ASSIST REPAIR	New	450.00	60.00
9	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	240.00	80.00
Gross Labour Cost (\$)			4,090.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >