

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012466/TVP3Q2**Date:** 20/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00002462201

Claimant Vehicle No : FBL6750S **Insured Vehicle No :** CB6338R

Date of Loss: 15/10/2022 Nature of Claim: TP Claim No: SNM22D207409/C0/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBL6750S**

Make & Model: HONDA CB190R, 184cc Engine No: WH161FMK16L00879

Reg. Date: 24/01/2017 (Man. Year: 2016) Chassis No: LWBPC103G1010666

Colour: Multi-colour Odometer: 0 km

Engine Capacity: 184 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 110/70 R17 Rear Tyre Size: 150/60 R17

Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 2,159.00 | 1,866.10 | 292.90 | 13.57 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 609.00 | 440.00 | 169.00 | 27.75 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 2,768.00 | 2,306.10 | 461.90 | 16.69 |
| Approved Total (Overridden) (S\$) | | 1,850.00 | | |
| (S\$) | 2,768.00 | 1,850.00 | 918.00 | 33.16 |
| + GST 7.00/7.00% (S\$) | 193.76 | 129.50 | 64.26 | 33.16 |
| Nett Amount (S\$) | 2,961.76 | 1,979.50 | 982.26 | 33.16 |

INSPECTION

Date of Assignment: 16/03/2023

Date Inspected: 13/12/2022 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | (Last Synchronised: 20 Mar 2023) | |
| Parts: | N/A | HONDA CB190R 184cc (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for FBL6750S) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|--|-----|----------|---|-----------|------------|------------|
| 1 | 2 | | *BALANCER HANDLE | Cut | 40.00 F | *40.00 FL |
| 2 | 1 | | *BAR HANDLE RH | Bent | 182.00 F | *182.00 FL |
| 3 | 1 | | *BOLT FOOTREST FRONT (UPPER) | Necessary | 10.00 F | *10.00 FL |
| 4 | 1 | | *BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT | Cut | 230.00 F | *230.00 FL |
| 5 | 1 | | *COVER A MUFFLER | Bent | 69.00 F | *69.00 FL |
| 6 | 1 | | *COVER B MUFFLER | Bent | 69.00 F | *69.00 FL |
| 7 | 1 | | *COVER SIDE | Cut | 255.00 F | *255.00 FL |
| 8 | 1 | | *FOOTREST FRONT RH | Broken | 58.00 F | *58.00 FL |
| 9 | 1 | | *FOOTREST REAR RH | Dented | 52.00 F | *52.00 FL |
| 10 | 1 | | *FOOTREST RUBBER | Missing | 16.00 F | *16.00 FL |
| 11 | 1 | | *HOLDER PILLION STEP RH | Dented | 69.00 F | *69.00 FL |
| 12 | 1 | | *LAMP SIGNAL FRONT RH | Cut | 103.00 F | *103.00 FL |
| 13 | 1 | | *LEVER BRAKE | Dented | 24.00 F | *24.00 FL |
| 14 | 1 | | *MIRROOR LH | Cut | 58.00 F | *58.00 FL |
| 15 | 1 | | *MIRROOR RH | Cut | 58.00 F | *58.00 FL |
| 16 | 1 | | *MUDGUARD FRONT | Cut | 128.00 F | *128.00 FL |
| 17 | 1 | | *PEDAL BRAKE COMP | Bent | 58.00 F | *58.00 FL |
| 18 | 1 | | *PEDAL BUSHING | Necessary | 12.00 F | *12.00 FL |
| 19 | 1 | | *STAND MAIN | Bent | 83.00 F | *83.00 FL |
| 20 | 1 | | *STAY HEADLAMP | Bent | 83.00 F | *83.00 FL |
| 21 | 1 | | *STICKER NUMBER PLATE FRONT (BLACK) | Necessary | 19.00 F | *19.00 FL |
| 22 | 1 | | *WINDSHIELD AFTER MARKET | Cracked | 203.00 F | *203.00 FL |
| 23 | 1 | | *METER IU (12V) NEW MODEL | Torn | 280.00 FS | *175.00 FS |
| F=Franchise part. S=SpcNett. L=ListItemDisc. | | | | | | |
| Sub Total (\$\$) | | | | | 2,159.00 | 2,054.00 |
| - List Item Discount on L Items 0.00/10.00% (\$\$) | | | | | 0.00 | 187.90 |
| Total Parts (\$\$) | | | | | 2,159.00 | 1,866.10 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|---------------|---------------|
| Labour Items | | | | |
| 1 | LABOUR | New | 548.80 | 400.00 |
| 2 | TRANSPORT CHARGES (MOTORCYCLE/ESCOOTER) | New | 60.20 | 40.00 |
| Gross Labour Cost (S\$) | | | 609.00 | 440.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >