

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012468/GNP3M4**Date:** 18/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00057142200
Claimant Vehicle No :	SJW1222E	Insured Vehicle No :	SNG6660C
Date of Loss:	09/12/2022	Nature of Claim: TP	Claim No: SNM22D208938/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW1222E	Engine No:	D4162T2482813
Make & Model:	VOLVO S60, 1.6 D2 (A)	Chassis No:	YV1FS84ABE2270254
Reg. Date:	25/03/2014 (Man. Year: 2013)	Odometer:	124870 km
Colour:	Red		
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,012.77	13,113.94	898.83	6.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,650.00	430.00	20.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,092.77	14,763.94	1,328.83	8.26
Approved Total (Overridden) (S\$)		11,800.00		
(S\$)	16,092.77	11,800.00	4,292.77	26.68
+ GST 8.00/8.00% (S\$)	1,287.42	944.00	343.42	26.68
Nett Amount (S\$)	17,380.19	12,744.00	4,636.19	26.68

INSPECTION

Date of Assignment:	16/12/2022	
Date Inspected:	13/12/2022	Inspected At: VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2023)
Parts:	143	VOLVO S60 1.6 D2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW1222E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	2,905.00 FL	*2,905.00 FL
2	1		*BOOTLID EMBLEM	Necessary	128.00 FL	*128.00 FL
3	1		*BOOTLID D2 EMBLEM	Necessary	98.40 FL	*68.00 FL
4	1		*BOOTLID S60 EMBLEM	Necessary	115.00 FL	*85.00 FL
5	1		*BOOTLID RH REFLECTOR	Cut	256.30 FL	*256.30 FL
6	1		*BOOTLID LH REFLECTOR	Cut	256.30 FL	*256.30 FL
7	1		*BOOTLID INNER LOCK	Bent	587.60 FL	*574.70 FL
8	1		*BOOTLID RUBBER	Twisted	192.70 FL	*192.70 FL
9	1		*RH TAILLAMP	Cut	511.70 FL	*511.70 FL
10	1		*LH TAILLAMP	Cut	511.70 FL	*511.70 FL
11	1		*RH TAILLAMP LOWER BRACKET	Not Necessary	108.70 FL	*- FL
12	1		*LH TAILLAMP LOWER BRACKET	Not Necessary	108.70 FL	*- FL
13	1		*REAR BUMPER	Deformed	2,087.70 FL	*2,087.70 FL
14	4		*REAR BUMPER PARKING SENSOR	Damaged	1,180.00 FL	*980.00 FL
15	1		*REAR BUMPER TOWING COVER	Not Necessary	92.00 FL	*- FL
16	1		*REAR BUMPER CENTER PAD - BLACK	Cut	780.10 FL	*780.10 FL
17	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	96.00 FL	*- FL
18	1		*REAR BUMPER LH SIDE RETAINER	Deformed	96.00 FL	*96.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	1,621.60 FL	*1,621.60 FL
20	10		*REAR BUMPER CLIPS	Necessary	120.00 FL	*30.00 FL
21	1		*REAR KEYLESS ANTENNA SENSOR	Broken	219.70 FL	*219.70 FL
22	1		*REAR END PANEL	Buckled	648.50 FL	*648.50 FL
23	1		*REAR END PANEL TOP TRIM	Deformed	435.00 FL	*435.00 FL
24	1		*REAR EXHAUST SILENCER	Bent	1,148.60 FL	*1,148.60 FL
25	1		*REAR EXHAUST SILENCER HEAT SHIELD	Bent	522.70 FL	*292.70 FL
26	1		*REAR SPARE TYRE PANEL TOP COVER	Broken	697.30 FL	*697.30 FL
27	1		*REAR NO.PLATE	Cut	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,565.30	14,566.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,552.53	1,452.66
Total Parts (\$\$)	14,012.77	13,113.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR DAMAGES	New	980.00	800.00
2	TO SPRAY PAINTING	New	1,100.00	850.00
Gross Labour Cost (S\$)			2,080.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >