



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 8471Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER FASCIA (WCP)	DISTORTED	170.00	170.00
1	FRONT BUMPER SIDE RETAINER RH (WCP)	DAMAGED	10.00	10.00
1	FRONT BUMPER REINFORCEMENT BEAM (WCP)	DENTED	180.00	180.00
1	FRONT BUMPER FOG LAMP COVER RH (WCP)	DISTORTED	15.00	15.00
1	FRONT BUMPER FOG LAMP RH (WCP)	DISTORTED	115.00	50.00
1	FRONT BUMPER TOWING COVER (WCP)	NECESSARY	12.00	12.00
1	FRONT BUMPER LOWER LIP (WCP)	DISTORTED	120.00	120.00
1	FRONT BUMPER DUST COVER (WCP)	NOT NECESSARY	70.00	-
1	FRONT BUMPER LOWER GRILLE (WCP)	NOT NECESSARY	55.00	-
1	FRONT FENDER RH (WCP)	BUCKLED	180.00	180.00
1	FRONT FENDER COWLING RH (WCP)	TORN	70.00	35.00
1	FRONT FENDER WHEEL ARCH GARNISH (WCP)	CUT	40.00	40.00
1	HEADLAMP RH (WCP)	CRACKED	780.00	780.00
1	HEADLAMP BRACKET RH (WCP)	CRACKED	20.00	20.00
1	HEADLAMP PANEL RH (WCP)	NOT NECESSARY	120.00	-
1	WHEEL HOUSE EXTENSION PANEL RH (WCP)	DISTORTED	100.00	100.00
1	WINDSCREEN WASHER TANK (WCP)	DEFORMED	45.00	45.00
1	WINDSCREEN WASHER TANK MOTOR (WCP)	NOT NECESSARY	35.00	-
1	HORN (WCP)	NOT NECESSARY	45.00	-
1	BONNET (WCP) (ADDITIONAL)	BUCKLED	380.00	380.00
1	FRONT SIDE FRAME GUSSET RH (WCP) (ADDITIONAL)	BENT	40.00	40.00
1	PLATE R SIDE FRAME (WCP) (ADDITIONAL)	BENT	35.00	35.00
1	HEADLAMP LH (WCP) (ADDITIONAL)	CRACKED	780.00	780.00
1	HEADLAMP BRACKET LH (WCP) (ADDITIONAL)	CRACKED	20.00	20.00
1	FRONT GRILLE (WCP) (ADDITIONAL)	CRACKED	180.00	180.00
1	FRONT FENDER ARCH GARNISH LH (WCP) (ADDITIONAL)	DEFORMED	40.00	40.00
	COST PLUS 15%		548.55	484.80
			4,205.55	3,716.80
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	20.00	20.00

Report Ref No. CS/LPC22012471/Any3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT FENDER COWLING CLIPS (SN)	NECESSARY	20.00	20.00
1	SET FRONT FENDER WHEEL ARCH GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
	COST PLUS 15%		9.00	-
			69.00	60.00
	LABOUR			
	CUT OUT, RENEW, KNOCKING & WELDING FRONT FENDER RH, FRONT WHEEL HOUSE EXTENSION PANEL RH, FRONT HEADLAMP PANEL RH, REMOVE & INSTALL ALL DAMAGE PARTS, STRAIGHTEN FRONT CHASSIS & RE-ALIGN BODY.		1,080.00	900.00
	COMPUTERISE WHEEL ALIGNMENT.		120.00	80.00
	SPRAY PAINTING ON DAMAGE PARTS.		1,200.00	1,000.00
	CHECK ALL LIGHTING AFTER REPAIRS.		35.00	30.00
			2,435.00	2,010.00
GRAND TOTAL			6,709.55	5,786.80
RECOMMENDED COST OF REPAIRS				5,786.80

Report Ref No. CS/LPC22012471/Any3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.