

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988**Our File No:** CS/EGI22012472/TQY3E2  
**Date:** 04/07/2023REFERENCEInsured/Claimant: LIM AH CHU Policy No: DMPG22009729  
Date of Loss: 03/12/2022 Nature of Claim: OD Claim No: CDMPG22002628DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNB6046C**  
Make & Model: M.G. HS, 1.5 (A) Engine No: 15E4E8AGM3310371  
Reg. Date: 31/08/2021 (Man. Year: 2021) Chassis No: LSJA24U97MN081892  
Colour: White Odometer: 24877 km  
Engine Capacity: 1490 cc  
Market Value/New Car Price: S\$125,000.00  
Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: YesCONDITION OF TYRESFront Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,169.50	4,117.00	52.50	1.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,170.00	5,440.00	730.00	11.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,339.50</b>	<b>9,557.00</b>	<b>782.50</b>	<b>7.57</b>
<b>- Excess (S\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>9,839.50</b>	<b>9,057.00</b>	<b>782.50</b>	<b>7.95</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>688.77</b>	<b>633.99</b>	<b>54.78</b>	<b>7.95</b>
<b>Nett Amount (S\$)</b>	<b>10,528.27</b>	<b>9,690.99</b>	<b>837.28</b>	<b>7.95</b>

INSPECTIONDate of Assignment: 13/12/2022  
Date Inspected: 15/12/2022 Inspected At: Trans Eurokars Pte Ltd (Ubi)  
5 Ubi Close  
Singapore 408605  
Estimated Period of Repair: 7.0 days**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2023)
<b>Parts:</b> M1-SUV	M.G. HS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SNB6046C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RH	Bent	780.00 F	*780.00 F
2	1		*QUARTER GLASS RH	Necessary	260.00 F	*260.00 F
3	1		*REAR DOOR RH	Bent	1,500.00 F	*1,500.00 F
4	1		*FILM STICKER NO.1 REAR DOOR RH	Necessary	67.00 F	*67.00 F
5	1		*UPPER FILM STICKER REAR DOOR RH	Necessary	52.00 F	*52.00 F
6	1		*FILM STICKER NO.2 REAR DOOR RH	Necessary	67.00 F	*67.00 F
7	1		*APPLIQUE REAR DOOR RH	Not Necessary	4.00 F	*- F
8	1		*WEATHERSTRIP DOOR REAR RH	Necessary	99.00 F	*99.00 F
9	1		*HANDLE REAR DOOR RH	Missing	58.00 F	*58.00 F
10	1		*CAP HANDLE REAR DOOR RH	Missing	26.00 F	*26.00 F
11	1		*GASKET HANDLE REAR DOOR RH	Necessary	2.50 F	*2.50 F
12	1		*BASE HANDLE REAR DOOR RH	Distorted	28.00 F	*28.00 F
13	1		*WHEEL ARCH REAR DOOR RH	Cut	58.00 F	*58.00 F
14	1		*WHEEL ARCH REAR FENDER RH	Cut	67.00 F	*67.00 F
15	1		*GARNISH LOWER DOOR REAR RH	Cut	150.00 F	*150.00 F
16	1		*GARNISH LOWER FRONT DOOR RH	Cut	241.00 F	*241.00 F
17	10		*CLIP	Necessary	20.00 F	*20.00 F
18	1		*LOWER MOULDING FRONT DOOR RH (SILVER)	Necessary	99.00 F	*99.00 F
19	1		*HANDLE FRONT DOOR RH	Cut	150.00 F	*150.00 F
20	1		*CAP HANDLE FRONT DOOR RH	Not Necessary	26.00 F	*- F
21	1		*GASKET FRONT DOOR RH	Not Necessary	2.50 F	*- F
22	1		*SIDE MIRROR RH	Cut	380.00 F	*380.00 F
23	1		*PLUG-FRT S/D/ O/S HDL ACC HOLE	Necessary	2.50 F	*2.50 F
24	5		*NUT-RR BPR FASCIA	Necessary	10.00 F	*10.00 F
25	1		*SUNDRIES	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$)</b>	<b>4,169.50</b>	<b>4,117.00</b>
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR FENDER RH AND REAR DOOR RH	New	2,640.00	2,640.00
2	TO RESPRAY REAR FENDER RH, REAR & FRONT DOOR RH, FRONT & REAR DOOR HANDLE RH AND COVER SIDE MIRROR	New	2,100.00	1,890.00
3	TO REMOVE & REFIT QUARTER GLASS RH AND CONDUCT WATER TEST LEAK	New	280.00	280.00
4	TO SUPPLY SEALANT ON THE QUARTER GLASS RH	New	80.00	80.00
5	TO SUPPLY SOLAR FILM QUARTER GLASS RH	New	140.00	140.00
6	TO TRANSFER REAR RH DOOR MECHANISMS	New	330.00	0.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	150.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	250.00	180.00
9	TO CARRY-OUT BODY CAVITY PRESERVATION. (INCLUDING NEW PARTS AND CAOUTCHOUC)	New	150.00	80.00
<b>Gross Labour Cost (\$)</b>			<b>6,170.00</b>	<b>5,440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >