



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 6366S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,800.00	-
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,600.00	1,025.00
2	FRONT BUMPER BRACKET (CONSISTENT)	BROKEN	350.00	270.00
1	FRONT RIGHT HEADLAMP (CONSISTENT)	CUT	2,000.00	2,000.00
1	FRONT RIGHT FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	1,200.00	-
1	FRONT BUMPER GRILL (CONSISTENT)	CUT	1,200.00	565.00
1	RADIATOR GRILL (CONSISTENT)	NOT NECESSARY	1,000.00	-
1	FRONT REINFORCEMENT BAR (CONSISTENT)	NOT NECESSARY	800.00	-
	LESS 20% DISCOUNT		-	-772.00
			9,950.00	3,088.00
LABOUR				
	REMOVE AND REFIT AND PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BONNET AND FRONT RIGHT FENDER .		1,000.00	400.00
	REMOVE, REFIT AND REPLACED DAMAGE AND CHECK UP REAR ELECTRICAL WIRING.		150.00	30.00
	REMOVE AND REFIT INNER GARNISHES TRIM TO ASSIST REPAIR .	NOT NECESSARY	200.00	-
	TO APPLY UNDERCOATING ON REPLACED PANEL.	NOT NECESSARY	120.00	-
	TO RESPRAY PAINTING.		1,000.00	800.00
			2,470.00	1,230.00
GRAND TOTAL			12,420.00	4,318.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,450.00

Report Ref No. CC4/ASM22012475/Gpa3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.