

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI22012482/KWP3Q2**Date:** 21/12/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000812
Claimant Vehicle No :	SHD903D	Insured Vehicle No :	SML9437Y
Date of Loss:	12/12/2022	Nature of Claim:	TP
		Claim No:	M2207118

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD903D		
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C003096
Reg. Date:	08/12/2017 (Man. Year: 2016)	Chassis No:	VF1ABL15AUC283407
Colour:	Metallic White/Red	Odometer:	635868 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Firenza 9 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,363.96	1,068.24	3,295.72	75.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,540.00	480.00	7,060.00	93.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,903.96	1,548.24	10,355.72	86.99
Approved Total (Overridden) (\$\$)		1,250.00		
(\$\$)	11,903.96	1,250.00	10,653.96	89.50
+ GST 7.00/7.00% (\$\$)	833.28	87.50	745.78	89.50
Nett Amount (\$\$)	12,737.24	1,337.50	11,399.74	89.50

INSPECTION

Date of Assignment:	20/12/2022		
Date Inspected:	13/12/2022	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2022)
Parts:	143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD903D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
7	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
8	1		*BUMPER BEAM REAR	Repair	547.80 FL	*- FL
9	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL
10	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
11	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
12	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*- FL
13	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
14	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
15	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
16	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
17	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
18	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
19	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
20	1		*LICENSE PLATE WITH HOLDER REAR	Serviceable	120.00 FS	*- FS
21	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
22	1		*RR BUMPER ADVERTISEMENT	Necessary	100.00 FS	*60.00 FS
23	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
24	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,671.96	1,165.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	308.00	97.36
Total Parts (\$\$)	4,363.96	1,068.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,000.00	200.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
6	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
Gross Labour Cost (S\$)			7,540.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >