

Enquire Vehicle Owner Details (As At 10 Dec 2020 / 16:30:00)

Vehicle Owner Details

Owner ID Type:

Business

Owner ID:

27504200J

Owner Name:

TEO BAK SOAH TRADING CO

Registered Address Type:

**Private Residential (Condo Apt or House) /
Shopping / Office Complexes**

Registered Block/House No.:

5

Registered Street Name:

CHIN BEE AVENUE

Registered Unit No.:

-

Registered Building Name:

-

Registered Postal Code:

619929

Vehicle Insurance Details

Vehicle No.:

XB2780Z

Make Description/Model:

**IVECO / TRAKKER AUTO AT260T41
(MY2013, EURO V)**

Insurance Company Name:

LIBERTY INS P L



Thank you

Ong Hwee Ling Pauline has successfully logged out.
Your last login date and time was 11 Dec 2020, 14:41:22.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(\$)
1	Vehicle	XB2780Z	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49

HIAP LEK AUTOMOBILE TRADING

160 Sin Ming Drive
Sin Ming Autocity
#05-17
Singapore 575722

Tel : 6453 1743 Fax: 6266 8605
E-Mail : hiaplek@hotmail.com

Date: 30th AUGUST 2022

Vehicle No : SDY 8187M
Make/ Model : MERCEDES BENZ E200 SEDAN EDITION E R18 LED
Year of Manufacture : 03 DECEMBER 5
Chassis No. : WDD2120342B228939
Colour : BLUE
Name : LOH AH TENG
Address : 29 AMBER ROAD
#03-03
Singapore 439942

QTY	ITEM/PARTICULARS	AMOUNT (S\$)
-----	------------------	--------------

1. Third Party Accident Claim for Motor Vehicle No. SDY 8187M
Date of Accident: 10th DECEMBER 2020

..... S\$10,650.00
(Lump Sum)

Singapore Dollars: TEN Thousand SIX Hundred and FIFTY Only

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singapore 415874
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

INVOICE

To : Loh Ah Teng
c/o : Hiap Lek Automobile Trading
160 Sin Ming Drive
#05-17 Sin Ming Autocity
Singapore 575722

Date : 30 Aug 2022
Invoice No. : 8094300

DESCRIPTION	AMOUNT
Service rendered for appraisal / inspection report :	
Professional inspection fees	SGD 751.00
Photographs 56 pcs	
Transport fees	
Re-inspection fees (work in progress, post repair inspection)	
Total	SGD 751.00
Singapore dollar : SEVEN HUNDRED FIFTY ONE ONLY.	
Registration no. : SDY8187M	
Make/Model : Mercedes Benz E200 Sedan Edition E R18 LED	
Our reference : UAM21.01.01-AK-STP-HLA-SDY8187M	
<i>!! payments made payee to:- UNITED APPRAISAL & MANAGEMENT PTE LTD</i>	



for UNITED APPRAISAL & MANAGEMENT PTE LTD

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singapore 415874
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

Dur ref. : UAM21.01.01-AK-STP-HLA-SDY8187M
Date : 30 Aug 2022

John Ah Teng

WITHOUT PREJUDICE

Dear Sir,

Re : Third Party Claim For Vehicle Registration No. SDY8187M

We refer to your instruction to appraise the above-mentioned vehicle on 04 January 2021

A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. Hiap Lek Automobile Trading for SGD 16,674.70 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly.

Our revised quotation for the repair is SGD 13,339.29. In our opinion, it to be excessive. Therefore, we recommend a contract lump-sum repair cost. This is more economical than to have the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair the above-mentioned vehicle for SGD 10,650.00 NETT. Which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirement at the recommended contract lump-sum. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs.

Under normal circumstances, the entire repair of the damaged vehicle should be completed within reasonable period of 7 (Seven) days.

We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisal schedule and invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Yours faithfully,
United Appraisal & Management Pte Ltd



Mananda K. Biswas Marc
Motor Vehicle Appraiser

Encs. :

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is prohibited.

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singapore 415874
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

VEHICLE INSPECTION REPORT

To : Loh Ah Teng

Our ref. : UAM21.01.01-AK-STP-HLA-SDY8187M

Date : 30 Aug 2022

REFERENCE

Assign by	: Loh Ah Teng	Insured	: To be advice
Assign on	: 04 Jan 2021	Policy no.	: To be advice
Inspection on	: 04 Jan 2021	Claim no.	: To be advice
Accident on	: 10 Dec 2020	Sum insured	: To be advice
Workshop name	: Hiap Lek Automobile Trading	Excess	: Not applicable
Inspection at	: 160 Sin Ming Drive #05-17 Sin Ming Autocity Singapore 575722	3rd party Veh.	: To be advice
		3rd party ins.	: To be advice

ARTICULARS OF DAMAGED VEHICLE

Registration no.	: SDY8187M	Odometer	: 119513 km
Make / Model	: Mercedes Benz E200 Sedan Edition E R18 LED	Chassis no.	: WDD2120342B228939
Regn. date	: 03 Dec 2015	Engine no.	: 27492030455808
Body colour	: Grey	Engine cap.	: 1991 cc

RE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)


Steering	: In order	Paintwork	: Good
Clutch/brake	: In order	Undercarriage	: Serviceable
Handbrake	: In order	Gen. condition	: Good

TYRE CONDITION ON VEHICLE

	Make	Size	Tread depth	Type of road wheel
Front N/S	: Michelin	245/40ZR18	70%	Alloy
Front O/S	: Michelin	245/40ZR18	70%	Alloy
Rear N/S	: Goodyear	265/35R18	70%	Alloy
Rear O/S	: Goodyear	265/35R18	70%	Alloy

NOTE: The above percentages represent the estimated remaining life of tyre threads.

* Denotes damaged component/s

POINT OF IMPACT**SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT**

The impact of the collision has damaged / affected the rear bumper, rear end panel, taillamp, o/s rear ender, rear undercarriage and etc...

Please refer to Annex A (Appraisal Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on 05 Jan 2021 for repair in progress.

RECOMMENDATION

The estimate cost of repair submitted by Messrs Hiap Lek Automobile Trading as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 10,650.00 to carry out the repairs. Please refer to Annex A (Appraisal Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would take approximately 7 (Seven) working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our appraisal Report, which includes evidence photographs.

Ours faithfully,
United Appraisal & Management Pte Ltd



Sanda K. Biswas Marc
Motor Vehicle Appraiser

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SDY8187M

Our reference : UAM21.01.01-AK-STP-HLA-SDY8187M

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adju Amt \$
<u>LIST ITEMS</u>					
1	1	Bootlid	Refer To Labour	0.00	X nn
2	1	Bootlid logo	Necessary	67.00	X nn
3	1	Bootlid emblem 'E200'	Necessary	72.00	X nn
4	1	Bootlid emblem '7G- Tronic '	Necessary	112.00	X nn
5	1	Bootlid reflector o/s	Not Necessary	324.00	X nn
6	1	Taillamp o/s	Cracked	942.00	✓ 94
7	1	Taillamp lower bracket o/s	Cracked	98.00	✓ 9
8	1	Rear bumper	Deformed 1501 ✓	1604.20	160
9	2	Rear bumper side retainer @ SGD 118.80	Distorted	237.60	✓ 23
10	1	Rear bumper side garnish @ SGD 167.20	Distorted	334.40	✓ 16
11	1	Rear bumper lower	Necessary 325 ✓	485.00	✓ 48
12	1	Rear bumper lower chrome moulding	Necessary 225 ✓	320.00	32
13	1	Rear bumper carrier / support	Cracked	219.00	X nn 21
14	1	Rear bumper reinforcement	Bend	520.00	X nn 52
15	1	Rear bumper sensor @ SGD 215.60	Malfunction 215.60 ✓	1293.60	129
16	1	Rear bumper sensor wire harness	Shorted	355.00	X nn 35
17	1	Rear end panel	Repair	928.00	X nn
18	1	Rear end panel top garnish	Re-Used	272.40	X nn
19	1	Rear exhaust heat shield A	Bend	165.00	X nn 16
20	1	Rear exhaust heat shield B	Bend	195.00	X nn 19
21	1	Rear fender o/s	Dented	995.00	✓ 99
22	1	Rear fender inner shield o/s	Torn	127.00	X nn 12
23	1	Rear fender air vent o/s	Cracked	94.50	X nn 9
24	1	Rear windscreen moulding	Necessary	234.00	✓ 23
25	1	Rear wheel hub bearing assy o/s	Impacted 304 ✓	385.00	38
				10379.70	868
				5411.60	
				-10%	
				4870.44	Less 0% / 10%
				0.00	868
				10379.70	7819

SPECIAL NETT ITEMS

1	1	Sundries	Necessary	50.00	30 ✓
2	1set	Rear bumper clips	Necessary	80.00	40 ✓ 80
3	1set	Taillamp clips o/s	Cut/Distorted	30.00	20 ✓ 30
4	1	Taillamp seal o/s	Necessary	30.00	25 X nn
5	1set	Rear fender inner shield clips o/s	Necessary	35.00	35 X nn
6	1	Rear windscreen primer and cleaner	Necessary	100.00	30 ✓ 100
7	1	Rear windscreen inner seal	Necessary	80.00	50 ✓ 80
8	1	Rear windscreen sealant	Necessary	100.00	40 ✓ 100
9	1	Rear tyre o/s R18	Abraided	380.00	300 X nn
0	1	Rear alloy rim o/s R18 AMG	Deep Grazed	1450.00	1450 900 ✓
				2335.00	2230
TOTAL				1110	12714.70 10049

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SDY8187M

Dur reference : UAM21.01.01-AK-STP-HLA-SDY8187M

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adju Amt \$
<u>LABOUR & MISC CHARGES</u>					
1		To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	1000 ✓	1500.00	1200
2		To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.	60 ✓	80.00	60
3		To remove and refit interior upholstery to facilitate the repair.	100 ✓	200.00	180
4		To remove and refit rear windscreen to facilitate the repair.	120 ✓	180.00	150
5		To remove and refit o/s rear undercarriage for replacement of part.	200 ✓	300.00	280
6		To remove and refit o/s rear tyre to replace o/s rear rim. To perform tyre balancing.	20 ✓	100.00	80
7		To conduct computerize full wheel alignment.	80 ✓	120.00	100
8		To measure, drill holes on replaced rear bumper, position and install pdc sensor, check and test on the distance and functions.	30 ✓	80.00	60
9		To apply undercoating on the accident repair and replaced panel for rust protection.	30 ✓	200.00	180
10		Supply spray paint material and necessary items to respray rear bumper, rear end panel, o/s rear fender and other affected area / panel.	600 ✓	1200.00	1000
			2240		
TOTAL				3960.00	3290
Type text here			8220.44		
Total Parts and Labour Cost of Repair				16674.70	13339
Less (Lumpsum repair adjustment)			L/S - 6576.35 = 6600		2689
Adjustment Parts and Labour Cost of Repair					10650

