

LKK Auto Consultants Pte Ltd

LKK Auto Consultants Pte L 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 1395T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	REAR BRAKE CHAMBER PUMP AIR HOSE RH @\$287.33 (SN)	BENT / CUT	574.66	574.66
2	REAR BRAKE CHAMBER PUMP AIR HOSE LH @\$287.33 (SN)	BENT / CUT	574.66	574.66
3	REAR AXLE BRAKE TUBE AIR HOSE @\$320.64 (SN)	BENT / TWISTED	961.92	961.92
4	REAR CLUTCH AIR LINE JOINT CENTER @\$43.69 (SN)	NECESSARY	174.76	174.76
1	REAR CENTER CLUTCH AIR LINE JOINT BRACKET (BIG) (SN)	BENT	834.70	834.70
2	REAR NUMBER PLATE LAMP @\$76.40 (SN)	BROKEN	152.80	152.80
1	REAR NUMBER PLATE (SN)	DENTED / BENT	40.00	40.00
1	REAR NUMBER PLATE BRACKET (SN)	BENT	85.00	85.00
1	REAR PLUG SCREW (SN)	NECESSARY	80.00	40.00
1	REAR CYLINDER PUMP BRAKE CHAMBER ASSY RH (SN)	NOT NECESSARY	1,483.61	-
1	REAR CYLINDER PUMP BRAKE CHAMBER ASSY LH (SN)	NOT NECESSARY	1,483.61	-
1	REAR LOAD SENSING VALVE ROD (SN)	NOT NECESSARY	53.18	-
1	REAR CENTER BRAKE AIR TANK (SN)	DENTED / AIR LEAKED	1,358.44	1,358.44
1	REAR LOAD SENSING VALVE DAMPER (SN)	NOT NECESSARY	1,580.42	-
2	REAR CNNECTOR @\$75.39 (SN)	NECESSARY	150.78	150.78
1	REAR WHEEL COWLING RH (SN)	TORN	456.20	456.20
1	REAR WHEEL COWLING BRACKET RH (SN)	TWISTED	115.00	115.00
1	REAR WHEEL MUD FLAP RH (SN)	BROKEN	72.00	72.00
1	REAR WHEEL MUD FLAP BRACKET RH (SN)	TWISTED	45.00	45.00
			10,276.74	5,635.92
	<u>LABOUR</u>			
	TO SPRAY PAINTING ON THE AFFECTED AREA.		800.00	400.00
	LABOUR CHARGES TO REPAIR & REPLACE ABOVE DAMAGED PARTS.		1,000.00	500.00
			1,800.00	900.00
	GRAND TOTAL		12,076.74	6,535.92



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		5,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/ASM22008496/Dqy3e2-1



Automotive Assessor / Investigator