



Your Ref: S2M049U5

Date: 11<sup>th</sup> Jan 2023

Our Ref: CS3/ASM22008496/Dqy3e2-1

**M/s Axa Insurance Pte Ltd**

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Oh Vale

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: XE 1395T  
INSURED VEHICLE: SHC 2542D  
ACCIDENT DATE: 27/08/2022**

We thank you for your instruction on 07/12/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of XE 1395T from M/s Constant Appraiser Services.
- b) Singapore Accident Statement of Vehicles XE 1395T and SHC 2542D.
- c) Police Report of Vehicles XE 1395T.
- d) Final Repair Bill of XE 1395T from M/s LYS Engineering.
- e) Colour damaged vehicle photographs of XE 1395T.

Pre-Repair Inspection Date: 07/09/2022 at M/s 245 Jalan Ahmad Ibrahim Singapore 629144,  
Repairer: LYS Engineering.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: XE 1395T
Make & Model	: Mitsubishi Fuso FP51SDR3VDEA
Year of Registration	: 2016
Chassis Number	: FP51SDA20003
Engine Capacity	: 11967 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.