

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22012489/KWY3Q2**Date:** 22/12/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : SML5734R**Insured Vehicle No :** WC8235Z

Date of Loss: 09/12/2022

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SML5734R**

Make & Model: RENAULT SCENIC III, 1.5 (A)

Engine No: K9KF649D059767

Reg. Date: 27/05/2019 (Man. Year: 2019)

Chassis No: VF1RFA00662894772

Colour: Metallic Red

Odometer: 237862 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R20

Rear Tyre Size: 195/55 R20

Front Left Side: Goodyear 8 mm

Rear Left Side: Goodyear 8 mm

Front Right Side: Goodyear 8 mm

Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,320.83	7,464.94	5,855.89	43.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	1,490.00	2,640.00	63.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,450.83	8,954.94	8,495.89	48.68
+ GST 7.00/7.00% (S\$)	1,221.56	626.85	594.71	48.68
Nett Amount (S\$)	18,672.39	9,581.79	9,090.60	48.68
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 13/12/2022

Date Inspected: 14/12/2022

Inspected At:

Munich Autocare Pte Ltd (HQ)

60 Jalan Lam Huat, #07-43

Singapore 737869

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$347.75 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Dec 2022)
Parts:	M1-MPV	RENAULT SCENIC III 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML5734R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	1,617.60 F	*- FL
2	1		*RADIATOR GRILLE BLACK	Serviceable	318.00 F	*- FL
3	1		*FRONT EMBLEM	Serviceable	200.40 F	*- FL
4	1		*FRONT PARKING SENSOR	Missing	668.64 F	*668.64 FL
5	1		*BLINDSPOT SENSOR	Missing	434.04 F	*434.04 FL
6	1		*FRONT BUMPER	Cracked	2,011.44 F	*2,011.44 FL
7	1		*FRONT BUMPER SIDE BRACKET RH	Cracked	185.52 F	*185.52 FL
8	1		*FRONT BUMPER LOWER LIP	Cut	517.21 F	*517.21 FL
9	1		*FRONT FENDER RH	Cracked	774.72 F	*774.72 FL
10	1		*FRONT DOOR	Bent	2,294.64 F	*2,294.64 FL
11	1		*ALLOY RIM 20 INCH GS4 S4	Dented	1,353.72 F	*1,353.72 FL
12	1		*HEADLAMP RH	Serviceable	1,071.00 F	*- FL
13	1		*FRONT BUMPER SENSOR HARNESS WIRE	*Check	219.72 F	*- FL
14	1		*SIDE MIRROR RH	Repair	1,027.20 F	*- FL
15	1		*FRONT WHEEL ARCH OUTER RH	Serviceable	357.98 F	*- FL
16	7		*BUMPER CLIP	Necessary	49.00 FS	*49.00 FS
17	10		*FENDER INNERSHIELD CLIP	Not Necessary	70.00 FS	*- FS
18	1		*TYRE	*Check	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,320.83	8,288.93
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	823.99
Total Parts (S\$)	13,320.83	7,464.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REFIX FRONT ACCIDENT PORTION ,FRONT BONNET ,FRONT BUMPER ,FRONT FENDER RH ,FRONT DOOR RH ,SIDE MIRROR RH ,RIM AND ALL THE EFFECTED AREA	New	1,800.00	600.00
2	TO CHECK ELECTRICAL WIRING FOR PROPER FUNCTION INCLUDING ADJUST OF HEADLAMP	New	120.00	20.00
3	TO DISMANTLE & RENEW PARKING SENSOR & BLINDSPORT SENSOR	New	120.00	60.00
4	TO APPLY RUST PROOFING TO ALL THE EFFECTED AREA	New	120.00	0.00
5	TO CONDUCT 4 WHEEL ALIGNMENT & BALANCING	New	120.00	60.00
6	TO TRANSFER DOOR INNERTRIM TO NEW DOOR	New	350.00	0.00
7	TO RESPRAY FRONT ACCIDENT PORTION ,FRONT BONNET ,FRONT BUMPER,FRONT FENDER RH ,FRONT DOOR RH ,SIDE MIRROR RH AND ALL THE EFFECTED AREA	New	1,500.00	750.00
Gross Labour Cost (\$\$)			4,130.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >