

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIS22012492/KQY3Q2**Date:** 21/02/2023REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SMP1337J**Insured Vehicle No :** SMJ173C

Date of Loss: 27/11/2022

Nature of Claim: TP

Claim No: 2022 22008500/FR

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMP1337J**

Make &amp; Model: TOYOTA NOAH, 1.8 (A)

Engine No: 2ZR0D99717

Reg. Date: 11/09/2019 (Man. Year: 2019)

Chassis No: ZWR800395757

Colour: Metallic Silver

Odometer: 191549 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R16

Rear Tyre Size: 195/65 R16

Front Left Side: Farroad 9 mm

Rear Left Side: Farroad 8 mm

Front Right Side: Farroad 9 mm

Rear Right Side: Farroad 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,575.52	4,441.11	4,134.41	48.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,635.00	860.00	1,775.00	67.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,210.52</b>	<b>5,301.11</b>	<b>5,909.41</b>	<b>52.71</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,210.52</b>	<b>4,200.00</b>	<b>7,010.52</b>	<b>62.54</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 13/12/2022

Date Inspected: 14/12/2022 Inspected At:

Lian Her Motors (Ang Mo Kio)

Blk 5038, Ang Mo Kio Industrial Park 2, #01-405

Singapore 569541

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2023)
Parts:	M1-MPV	TOYOTA NOAH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP1337J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	878.90 FL	*- FL
2	1		*FRONT N/S BONNET HINGE	Repair	155.20 FL	*- FL
3	1		*FRONT WINDSCREEN RUBBER SEAL	Serviceable	95.20 FL	*- FL
4	1		*FRONT N/S FENDER	Buckled	988.80 FL	*911.20 FL
5	1		*FRONT N/S FENDER EMBLEM	Necessary	65.10 FL	*65.10 FL
6	1		*FRONT N/S FENDER INNERSHIELD	Distorted / Cracked	255.80 FL	*255.80 FL
7	1		*FRONT N/S HEADLAMP ASSY	Mtg Cracked	3,400.30 FL	*3,001.75 FL
8	1		*FRONT N/S HEADLAMP GARNISH	Mtg Cracked	155.20 FL	*155.20 FL
9	1		*FRONT TOP GRILLE	Serviceable	1,030.60 FL	*- FL
10	1		*FRONT TOP GRILLE COVER	Serviceable	225.60 FL	*- FL
11	1		*FRONT GRILLE TOP CHROME MOULDING	Serviceable	175.20 FL	*- FL
12	1		*FRONT GRILLE CENTRE CHROME MOULDING	Serviceable	175.20 FL	*- FL
13	1		*FRONT LOWER GRILLE	Serviceable	222.80 FL	*- FL
14	2		*FRONT LOWER GRILLE CHROME MOULDING	Serviceable	210.20 FL	*- FL
15	1		*FRONT BUMPER -COLOUR CODE	Cracked	1,375.20 FL	*1,288.20 FL
16	1		*FRONT N/S BUMPER SIDE RETAINER	Distorted	95.20 FL	*95.20 FL
17	1		*FRONT N/S BUMPER FOG LAMP GARNISH	Scratched	95.70 FL	*95.70 FL
18	1		*FRONT SUPPORT PANEL	Repair	1,780.50 FL	*- FL
19	20		*BUMPER CLIP	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,420.70	5,908.15
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,845.18	1,467.04
Total Parts (\$\$)	8,575.52	4,441.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING WELDING & CUTTING	New	1,200.00	400.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	1,200.00	440.00
3	CHECK /RECONNECT WIRING	New	35.00	20.00
4	REMOVE /REFIT AIR CON CONDENSER AND TO TOP UP GAS	New	200.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,635.00</b>	<b>860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >