

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : LAM CHUN HAN
C/O TUCK LIFE PTE LTD
25 Kaki Bukit Road 4, #01-68
Synergy@KB, Singapore 417800

Date : 15 March 2022
Our Ref : WG/TP/2022-54

REFERENCE PARTICULARS

Date of Accident : 10 February 2022
Date of Inspection : 03 March 2022

Type of Inspection : Third Party Claim
Date of Re-Inspn : 14 March 2022

VEHICLE PARTICULARS

Registration No : JTF8403
Make : Yamaha
Model : R15
Year : Na

Engine No : Na
Chassis No : Na
Odometer : 20260km
Colour : Blue

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front side	: Bridgestone	90/80-17
Rear Side	: Bridgestone	130/70-17

Thread Balance
5 mm
5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front and right side portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$6,900.00** nett at lump sum basis. (Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Five (05) working days.

Enclosed Eighty-two (82) photographs depicting damage to the vehicle.

Inspection conducted at : TUCK LIFE PTE LTD
25 Kaki Bukit Road 4, #01-68, Synergy@KB, Singapore 417800

In accordance to your instruction, we have **not authorise** repairs and inspection was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

VEHICLE NO : JTF8403
MODEL : R15

Our Ref : WG/TP/2022-54

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION	
01 FRONT FENDER	1	CRACKED	\$ 185.00	\$ 185.00	✓
02 HEADLAMP FAIRING	1	CRACKED	\$ 550.00	\$ 550.00	✓
03 HEADLAMP FAIRING SIDE GARNISH RH	1	GRAZED	\$ 244.00	\$ 244.00	✓
04 FRONT HEADLAMP	1	GRAZED	\$ 1,044.00	\$ 1,044.00	380 ✓
05 RH SIDE FAIRING	1	GRAZED/CRACKED	\$ 583.00	\$ 583.00	450 ✓
06 RH SIDE FAIRING GARNISH	1	GRAZED/CRACKED	\$ 368.00	\$ 368.00	✓
07 MUFFLER COMP I	1	DENTED	\$ 579.00	\$ 579.00	X nn
08 CAP	1	GRAZED	\$ 65.00	\$ 65.00	X nn
09 PROTECTOR MUFFLER I	1	GRAZED	\$ 193.00	\$ 193.00	✓
10 TAILLAMP FAIRING RH	1	GRAZED/CRACKED	\$ 459.00	\$ 459.00	X nn
11 FRONT BRAKE CAPILER	1	JAMMED	\$ 412.00	\$ 412.00	X nn
12 HANDLE BAR LH	1	BENT	\$ 239.00	\$ 239.00	125 ✓
13 HANDLE BAR RH	1	NOT NECESSARY	\$ 239.00	\$ -	X nn
14 GRIP LH	1	NOT NECESSARY	\$ 58.00	\$ 58.00	✓ cut
15 BALANCER LH	1	GRAZED	\$ 39.00	\$ 39.00	30 ✓
16 WING MIRORR LH	1	GRAZED	\$ 87.00	\$ 87.00	✓
17 FRONT BRAKE LEVER	1	GRAZED	\$ 49.00	\$ 49.00	35 ✓
18 BRAKE PEDAL FOOTRESR ASSY	1	BENT	\$ 482.00	\$ 482.00	135 ✓
19 FRONT FORK LH	1	BENT local repair	\$ 689.00	\$ 689.00	200 nett
20 FRONT FORK RH	1	BENT local repair	\$ 689.00	\$ 689.00	200 nett
21 CROWN HANDLE	1	NOT NECESSARY	\$ 330.00	\$ -	X nn
22 REAR PILLION FOOTREST LH	1	GRAZED	\$ 75.00	\$ 75.00	X nn
			\$ 7,658.00	\$ 7,089.00	
		Less 10%	\$ 765.80	\$ 708.90	
			\$ 6,892.20	\$ 6,380.10	
		2840 -10% 2556			400 nett

B) S/NETT ITEM

23 GEAR SHIT SHAFT OIL SEAL	1	NECESSARY	\$ 24.00	\$ 24.00	20 ✓
24 FORK OIL SEAL	1	NECESSARY	\$ 120.00	\$ 100.00	40 ✓
25 FORK OIL	1	NECESSARY	\$ 60.00	\$ 50.00	40 ✓
26 REAR BOX	1	GRAZED	\$ 600.00	\$ 500.00	250 ✓
27 REAR BOX BRACKET	1	BENT	\$ 200.00	\$ 180.00	100 ✓
			\$ 1,004.00	\$ 854.00	
					450

Parts Total :

\$ 7,896.20	\$ 7,234.10
-------------	-------------

C) LABOUR CHARGES & MISC

28 REPLACE , REALIGN AND ADJUST ABOVE DAMGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM	\$ 600.00	\$ 400.00	200 ✓
29 TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING	\$ 400.00	\$ 350.00	150 ✓
30 TO REMOVE/REFIT, REPLACE FRONT FORK TUDES	\$ 300.00	\$ 250.00	100 ✓
31 SPRAY PAINTING	\$ 450.00	\$ 400.00	300 ✓
Labour Total :	\$ 1,750.00	\$ 1,400.00	
			750

Total Parts and Laboure :

\$ 9,646.20	\$ 8,634.10
-------------	-------------

FINAL LUMP SUM ADJUSTMENT

4156

L/S - 3324.80
= 3300

\$ 6,900.00

4 days

POINT OF IMPACT

The impact was confined to the front and right side portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.


ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **S\$6,900.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully,
WG APPRAISAL SERVICES



Winson Goh
Automotive Appraiser



