

# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647. Singapore 542224  
Email: winsongkk@hotmail.com Contact: 9747 0063  
Company Register No. 53326249J

## ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : LAM CHUN HAN  
C/O TUCK LIFE PTE LTD  
25 Kaki Bukit Road 4, #01-68  
Synergy@KB, Singapore 417800

Date : 15 March 2022  
Our Ref : WG/TP/2022-54

### REFERENCE PARTICULARS

Date of Accident : 10 February 2022  
Date of Inspection : 03 March 2022

Type of Inspection : Third Party Claim  
Date of Re-Inspn : 14 March 2022

### VEHICLE PARTICULARS

Registration No : JTF8403  
Make : Yamaha  
Model : R15  
Year : Na

Engine No : Na  
Chassis No : Na  
Odometer : 20260km  
Colour : Blue

### CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good  
Foot Brake : Serviceable  
Hand Brake : Serviceable

General Body Work : Good  
Steering : Serviceable  
Lightings : Serviceable

### TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front side	: Bridgestone	90/80-17
Rear Side	: Bridgestone	130/70-17

Thread Balance
5 mm
5 mm

### GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front and right side portion.  
For details, refer to assessment for repairs and photographs attached.

### ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$6,900.00** nett at lump sum basis. (Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Five ( 05 ) working days.

Enclosed Eighty-two ( 82 ) photographs depicting damage to the vehicle.

Inspection conducted at : TUCK LIFE PTE LTD  
25 Kaki Bukit Road 4, #01-68. Synergy@KB, Singapore 417800

In accordance to your instruction, we have **not authorise** repairs and inspection was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

VEHICLE NO : JTF8403  
MODEL : R15

Our Ref : WG/TP/2022-54

**ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS**

**DESCRIPTION OF PARTS AND NATURE OF REPAIRS**

SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
01 FRONT FENDER	1	CRACKED	\$ 185.00	\$ 185.00
02 HEADLAMP FAIRING	1	CRACKED	\$ 550.00	\$ 550.00
03 HEADLAMP FAIRING SIDE GARNISH RH	1	GRAZED	\$ 244.00	\$ 244.00
04 FRONT HEADLAMP	1	GRAZED	\$ 1,044.00	\$ 1,044.00
05 RH SIDE FAIRING	1	GRAZED/CRACKED	\$ 583.00	\$ 583.00
06 RH SIDE FAIRING GARNISH	1	GRAZED/CRACKED	\$ 368.00	\$ 368.00
07 MUFFLER COMP I	1	DENTED	\$ 579.00	\$ 579.00
08 CAP	1	GRAZED	\$ 65.00	\$ 65.00
09 PROTECTOR MUFFLER I	1	GRAZED	\$ 193.00	\$ 193.00
10 TAILLAMP FAIRING RH	1	GRAZED/CRACKED	\$ 459.00	\$ 459.00
11 FRONT BRAKE CAPILER	1	JAMMED	\$ 412.00	\$ 412.00
12 HANDLE BAR LH	1	BENT	\$ 239.00	\$ 239.00
13 HANDLE BAR RH	1	NOT NECESSARY	\$ 239.00	\$ -
14 GRIP LH	1	NOT NECESSARY	\$ 58.00	\$ 58.00
15 BALANCER LH	1	GRAZED	\$ 39.00	\$ 39.00
16 WING MIRORRH LH	1	GRAZED	\$ 87.00	\$ 87.00
17 FRONT BRAKE LEVER	1	GRAZED	\$ 49.00	\$ 49.00
18 BRAKE PEDAL FOOTRESR ASSY	1	BENT	\$ 482.00	\$ 482.00
19 FRONT FORK LH	1	BENT	\$ 689.00	\$ 689.00
20 FRONT FORK RH	1	BENT	\$ 689.00	\$ 689.00
21 CROWN HANDLE	1	NOT NECESSARY	\$ 330.00	\$ -
22 REAR PILLION FOOTREST LH	1	GRAZED	\$ 75.00	\$ 75.00
			\$ 7,658.00	\$ 7,089.00
		Less 10%	\$ 765.80	\$ 708.90
			<b>\$ 6,892.20</b>	<b>\$ 6,380.10</b>

**B) S/NETT ITEM**

23 GEAR SHIT SHAFT OIL SEAL	1	NECESSARY	\$ 24.00	\$ 24.00
24 FORK OIL SEAL	1	NECESSARY	\$ 120.00	\$ 100.00
25 FORK OIL	1	NECESSARY	\$ 60.00	\$ 50.00
26 REAR BOX	1	GRAZED	\$ 600.00	\$ 500.00
27 REAR BOX BRACKET	1	BENT	\$ 200.00	\$ 180.00
			<b>\$ 1,004.00</b>	<b>\$ 854.00</b>

**Parts Total :**

<b>\$ 7,896.20</b>	<b>\$ 7,234.10</b>
--------------------	--------------------

**C) LABOUR CHARGES & MISC**

28 REPLACE , REALIGN AND ADJUST ABOVE DAMGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM			\$ 600.00	\$ 400.00
29 TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING			\$ 400.00	\$ 350.00
30 TO REMOVE/REFIT, REPLACE FRONT FORK TUDES			\$ 300.00	\$ 250.00
31 SPRAY PAINTING			\$ 450.00	\$ 400.00
<b>Labour Total :</b>			<b>\$ 1,750.00</b>	<b>\$ 1,400.00</b>

**Total Parts and Laboure :**

<b>\$ 9,646.20</b>	<b>\$ 8,634.10</b>
--------------------	--------------------

**FINAL LUMP SUM ADJUSTMENT**

<b>\$ 6,900.00</b>
--------------------

**POINT OF IMPACT**

The impact was confined to the front and right side portion of the vehicle.  
The damages appeared to be consistent as per the accident report statement.  
Please refer the attached schedule and photographs for details.

**ADJUSTMENT/RECOMMENDATIONS**

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

**CONCLUSION**

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **S\$6,900.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully,  
WG APPRAISAL SERVICES



---

Winson Goh  
Automotive Appraiser







































































