



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JTF 8403

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER	CRACKED	185.00	185.00
1	HEADLAMP FAIRING	CRACKED	550.00	550.00
1	HEADLAMP FAIRING SIDE GARNISH RH	GRAZED	244.00	244.00
1	FRONT HEADLAMP	GRAZED	1,044.00	380.00
1	RH SIDE FAIRING	GRAZED / CRACKED	583.00	450.00
1	RH SIDE FAIRING GARNISH	GRAZED / CRACKED	368.00	368.00
1	MUFFLER COMP 1	NOT NECESSARY	579.00	-
1	CAP	NOT NECESSARY	65.00	-
1	PROTECTOR MUFFLER 1	GRAZED	193.00	193.00
1	TAILLAMP FAIRING RH	NOT NECESSARY	459.00	-
1	FRONT BRAKE CAPILER	NOT NECESSARY	412.00	-
1	HANDLE BAR LH	BENT	239.00	125.00
1	HANDLE BAR RH	NOT NECESSARY	239.00	-
1	GRIP LH	CUT	58.00	58.00
1	BALANCER LH	GRAZED	39.00	30.00
1	WING MIRROR LH	GRAZED	87.00	87.00
1	FRONT BRAKE LEVER	GRAZED	49.00	35.00
1	BRAKE PEDAL FOOTREST ASSY	BENT	482.00	135.00
1	CROWN HANDLE	NOT NECESSARY	330.00	-
1	REAR PILLION FOOTREST LH	NOT NECESSARY	75.00	-
	LESS 10% DISCOUNT		-628.00	-284.00
			5,652.00	2,556.00
1	FRONT FORK LH (SN) (LOCAL REPAIR)	BENT	689.00	200.00
1	FRONT FORK RH (SN) (LOCAL REPAIR)	BENT	689.00	200.00
	LESS 10% DISCOUNT		-137.80	-
			1,240.20	400.00
	<u>SPECIAL NETT ITEMS</u>			
1	GEAR SHIT SHAFT OIL SEAL (SN)	NECESSARY	24.00	20.00

Report Ref No. CS3/CTI22001887/Twp3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FORK OIL SEAL (SN)	NECESSARY	120.00	40.00
1	FORK OIL (SN)	NECESSARY	60.00	40.00
1	REAR BOX (SN)	GRAZED	600.00	250.00
1	REAR BOX BRACKET (SN)	BENT	200.00	100.00
			1,004.00	450.00
	LABOUR			
	REPLACE, REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM.		600.00	200.00
	TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING.		400.00	150.00
	TO REMOVE/REFIT, REPLACE FRONT FORK TUDES.		300.00	100.00
	SPRAY PAINTING.		450.00	300.00
			1,750.00	750.00
GRAND TOTAL			9,646.20	4,156.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,300.00
---	--	--	-----------------

Report Ref No. CS3/CTI22001887/Twp3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.