

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22012493/RWY3Q2**Date:** 13/01/2023REFERENCE

Handling Insurer: HL Assurance Pte Ltd Policy No:

Claimant Vehicle No : SMY2703G **Insured Vehicle No :** SLV648Z

Date of Loss: 10/12/2022 Nature of Claim: TP Claim No: MPC03876/RL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY2703G**

Make & Model: HONDA ODYSSEY, 2.4 EXV (A) Engine No: K24W72501501

Reg. Date: 25/02/2021 (Man. Year: 2020) Chassis No: JHMRC1890LC203885

Colour: White Odometer: 20303 km

Engine Capacity: 2356 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,997.84	1,742.97	7,254.87	80.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,980.00	6,000.00	6,980.00	53.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,977.84	7,742.97	14,234.87	64.77
+ GST 8.00/8.00% (S\$)	1,758.23	619.44	1,138.79	64.77
Nett Amount (S\$)	23,736.07	8,362.41	15,373.66	64.77

INSPECTION

Date of Assignment: 14/12/2022

Date Inspected: 19/12/2022 Inspected At: Kah Motor Co Sdn Bhd (ALEXANDRA)
255 ALEXANDRA ROAD
Singapore -

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2023)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 EXV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY2703G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE WITH CASING	Not Necessary	45.00 FS	*- FS
2	1		*GLASS SET ,RR WINDSHIELD	Not Necessary	811.65 FS	*- FS
3	2		*MOLDINGRR.WINDSHIELD SIDE	Necessary	28.80 FS	*28.80 FS
4	1		*MOLDINGR.RR.WINDSHIELD CORNER	Necessary	13.57 FS	*13.57 FS
5	1		*MOLDINGL.RR.WINDSHIELD CORNER	Necessary	13.57 FS	*13.57 FS
6	4		*SPACERRR.W/SHIELD	Necessary	12.60 FS	*12.60 FS
7	1		*RUBBER A WINDSHIELD DAM	Necessary	2.92 FS	*2.92 FS
8	1		*DAMPERSTD 5X5	Necessary	6.82 FS	*6.82 FS
9	1		*CAPPIVOT	Necessary	3.90 FS	*3.90 FS
10	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
11	1		*TAILGATE COMP	Bent	859.65 FS	*859.65 FS
12	1		*WEATHERSTRIPTAILGATE	Not Necessary	94.27 FS	*- FS
13	1		*EMBEMH	Necessary	21.15 FS	*21.15 FS
14	1		*EMBEM.RR	Necessary	24.90 FS	*24.90 FS
15	1		*FACE ASSY,RR BUMPER	Deformed	421.50 FS	*421.50 FS
16	1		*SPACERR.RR.BUMPER SIDE	Necessary	15.30 FS	*15.30 FS
17	1		*SPACERL.RR.BUMPER SIDE	Necessary	15.30 FS	*15.30 FS
18	1		*CLIP BUMPER (7 PCS)	Necessary	12.07 FS	*12.07 FS
19	1		*PANEL COMP.REAR	Not Necessary	369.90 FS	*- FS
20	1		*PAN SET 3RD SEAT	Not Necessary	271.27 FS	*- FS
21	1		*LIGHT ASSY ,R.LID	Not Necessary	310.05 FS	*- FS
22	1		*LIGHT ASSY ,L.LID	Not Necessary	286.42 FS	*- FS
23	1		*LIGHT ASSY ,R.LID	Not Necessary	672.90 FS	*- FS
24	1		*LIGHT ASSY ,L.LID	Not Necessary	672.90 FS	*- FS
25	4		*RETAINER ,PARKING	Not Necessary	134.10 FS	*- FS
26	4		*SENSOR ASSY,PARKING BACK SENSOR	Not Necessary	860.10 FS	*- FS
27	1		*LINING ASSYRR.PANEL	Not Necessary	83.17 FS	*- FS
28	1		*REFLECTOR ASSYR.RR	Not Necessary	36.37 FS	*- FS
29	1		*REFLECTOR ASSYL.RR	Not Necessary	36.37 FS	*- FS
30	1		*FACER.RR.BUMPER GARNISH	Not Necessary	63.52 FS	*- FS
31	1		*FACEL.RR.BUMPER GARNISH	Not Necessary	63.52 FS	*- FS
32	1		*SPOILER ASSY ,R.RR	Not Necessary	79.20 FS	*- FS
33	1		*SPOILER ASSY ,L.RR	Not Necessary	79.20 FS	*- FS
34	1		*LOCKTAILGATE	Not Necessary	148.80 FS	*- FS
35	1		*GARNISH ASSY,RR.LICEION LID	Not Necessary	131.85 FS	*- FS
36	1		*MOLDING ASSYRR.LICENSE GARN	Cut	140.92 FS	*140.92 FS
37	1		*GUTTER COMPR.RR.PILLAR	Not Necessary	105.67 FS	*- FS
38	1		*GUTTER COMPL.RR.PILLAR	Not Necessary	105.67 FS	*- FS
39	1		*COVER COMPL.SLIDE DR CTR RAIL	Not Necessary	132.15 FS	*- FS
40	1		*BOLT TAIL LIGHT	Not Necessary	3.00 FS	*- FS
41	1		*ANTENNA ASSY,L.RR	Not Necessary	48.60 FS	*- FS
42	1		*BUZZER ASSYSMART	Not Necessary	48.22 FS	*- FS
43	1		*OILSHEET	Not Necessary	32.62 FS	*- FS
44	1		*STOPPERTAILGATE	Not Necessary	2.85 FS	*- FS
45	1		*LINING ASSYTAILGATE LOWER	Not Necessary	165.60 FS	*- FS

Report was unsubmitted during this print-out.

1/13/23, 1:43 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*GARNISH ASSYR, TAILGATE SIDE	Not Necessary	33.15 FS	*- FS
47	1		*POCKETTAILGATE LINING PULL	Not Necessary	8.62 FS	*- FS
48	1		*GARNISH ASSYL. TAILGATE SIDE	Not Necessary	33.15 FS	*- FS
49	1		*LINING COMP.R.RR.SIDEGATE	Not Necessary	589.42 FS	*- FS
50	1		*COMP LIDTOOL	Not Necessary	49.27 FS	*- FS
51	1		*LINING COMP ,L.RR.SIDE	Not Necessary	566.32 FS	*- FS
52	1		*SUNDRIES	Necessary	110.00 FS	*30.00 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	8,997.84 1,742.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	250.00	250.00
2	REMOVE & RENEW REVERSE SENSORS	New	250.00	250.00
3	BODY JOINT SEALANT TAILGATE	New	120.00	100.00
4	BODY JOINT SEALANT REAR PANEL	New	120.00	-
5	BODY JOINT SEALANT FLOOR PANEL	New	120.00	0.00
6	BODY UNDERSIDE COATING	New	520.00	0.00
7	APPLY BODY UNDERSIDE COATING	New	520.00	0.00
8	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	650.00	580.00
9	RESET VEHICLE SMART ENTRY SYSTEM	New	650.00	580.00
10	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	650.00	0.00
11	REMOVE & INSTALL RR WINDSCREEN	New	650.00	650.00
12	WINDSCREEN DAM KIT	New	120.00	120.00
13	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	650.00	650.00
14	CUT & RENEW RR FLOOR PANEL STRAIGHTEN FENDERS ALIG	New	4,000.00	1,300.00
15	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,150.00	1,040.00
16	REMOVE AND RE-INSTALL TAILGATE SPOILER	New	560.00	480.00
Gross Labour Cost (S\$)			12,980.00	6,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >