

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22012498/AQP3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00007682200

**Claimant Vehicle No :** SDK1237Y **Insured Vehicle No :** SJK8523D

Date of Loss: 10/12/2022 Nature of Claim: TP Claim No: SNM22D208937/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SDK1237Y**

Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) Engine No: CVK078768

Reg. Date: 27/04/2019 (Man. Year: 2019) Chassis No: WAUZZZF54KA036756

Colour: Grey Odometer: 45491 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	18,531.00	10,909.00	7,622.00	41.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,272.00	2,672.00	600.00	18.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>21,803.00</b>	<b>13,581.00</b>	<b>8,222.00</b>	<b>37.71</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>1,744.24</b>	<b>1,086.48</b>	<b>657.76</b>	<b>37.71</b>
<b>Nett Amount (S\$)</b>	<b>23,547.24</b>	<b>14,667.48</b>	<b>8,879.76</b>	<b>37.71</b>

**INSPECTION**

Date of Assignment: 14/12/2022

Date Inspected: 14/12/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2023)
<b>Parts:</b>	143	AUDI A5 2.0 SB TFSI S TRONIC (DESIGN) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDK1237Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,493.00 FS	*2,493.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	425.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP -LH/RH	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	254.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE LH	Not Necessary	72.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	2,576.00 FS	*- FS
8	2		*FRONT PARKING AID SENSOR SUPPORT -LH/RH	Not Necessary	116.00 FS	*- FS
9	1		*RADIATOR GRILLE COVER -UPPER	Not Necessary	209.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Not Necessary	529.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	139.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
13	1		*FRONT BUMPER GUIDE SECTION -LH	Not Necessary	41.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
15	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
16	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
17	1		*LOCK CARRIER BRACKET	Not Necessary	154.00 FS	*- FS
18	2		*FRONT BUMPER SUPPORT -LH/RH	Not Necessary	64.00 FS	*- FS
19	1		*HORN HIGH TONE -LH	Not Necessary	134.00 FS	*- FS
20	1		*HORN BRACKET -LH	Not Necessary	33.00 FS	*- FS
21	2		*FRONT PARKING AID SENSOR -INNER /OUTER	Not Necessary	532.00 FS	*- FS
22	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
23	1		*HEADLIGHT -LH	Cut	8,416.00 FS	*8,416.00 FS
24	1		*LIFT CYLINDER -LH	Not Necessary	217.00 FS	*- FS
25	1		*LIFT CYLINDER BRACKET-LH	Not Necessary	17.00 FS	*- FS
26	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	100.00 FS	*- FS
27	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
28	2		*RADIATOR AIR GUIDE -LH /RH INNER	Not Necessary	72.00 FS	*- FS
29	2		*RADIATOR AIR GUIDE -LH /RH OUTER	Not Necessary	38.00 FS	*- FS
30	2		*RADIATOR AIR GUIDE -UPPER /LOWER	Not Necessary	44.00 FS	*- FS
31	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
32	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **18,531.00**    **10,909.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	400.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	800.00
4	TO RESPRAY FRONT BUMPER	New	1,000.00	800.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,272.00	2,672.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >