




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

PRE-REPAIR INSPECTION REPORT				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS3/LIP22012501/Kny3m4 Date: 16/12/2022 Code: LIP	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMM 3573X	Veh. Inspected	SNA 1722Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS22/3467	Excess (\$)	0.00
	Assign From	TED SEAH	Assign Date	13/12/2022
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN TOURAN (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WVGZZZ1TZFW020573	Colour	WHITE
	Odometer	206426 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	BRIDGESTONE	2 mm
	L/H Front Tyre	225/45 R17	BRIDGESTONE	2 mm
	R/H Rear Tyre	225/45 R17	FALKEN	5 mm
	L/H Rear Tyre	225/45 R17	FALKEN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
	Accident Date	08/12/2022	Inspect Date / Time	14/12/2022 (01:24 PM)
	Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)REGISTRATION DATE: 14 JAN 2015 B)MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$23,997.00=NETT VALUE: \$16,003.00 C) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. D) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. E) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. F) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000			
5b. Estimate Days of Repair				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

	ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
--	-------------------------------------	----------------

Report Ref No. CS3/LIP22012501/Kny3m4

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.