

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012503/AVP3Q2**Date:** 27/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00005592200
Claimant Vehicle No :	SMT9819L	Insured Vehicle No :	SMZ489H
Date of Loss:	10/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D208906/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT9819L	Engine No:	PE31567566
Make & Model:	MAZDA CX-30, 2.0 LUXURY (A)	Chassis No:	JM6DM2W7AL0100932
Reg. Date:	27/07/2020 (Man. Year: 2020)	Odometer:	50177 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R18	Rear Tyre Size:	215/55 R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,967.50	10,573.60	7,393.90	41.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	1,610.00	1,660.00	50.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,237.50	12,183.60	9,053.90	42.63
Approved Total (Overridden) (S\$)		9,700.00		
Nett Amount (S\$)	21,237.50	9,700.00	11,537.50	54.33

INSPECTION

Date of Assignment:	15/12/2022	
Date Inspected:	14/12/2022 Inspected At:	Sin Yu Sin Workshop (HQ) 1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit) Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2023)
Parts:	M1-SUV	MAZDA CX-30 2.0 LUXURY (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT9819L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,794.40 F	*1,020.40 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER SIDE HOLDER LH	Damaged	64.60 F	*64.60 FL
4	1		*FRONT BUMPER ARC PROTECTOR LH	Deformed	221.40 F	*221.40 FL
5	1		*FRONT BUMPER ARC PROTECTOR CLIPS	Necessary	30.00 FS	*30.00 FS
6	1		*FRONT BUMPER SENSOR	Damaged (1 PCS ONLY)	480.40 F	*240.20 FL
7	1		*FRONT BUMPER DAY LIGHT LH	Cracked	688.10 F	*688.10 FL
8	1		*FRONT BUMPER DAY LIGHT HOUSING LH	Damaged	62.40 F	*62.40 FL
9	1		*FRONT BUMPER INNER SIDE COVER	Torn	69.40 F	*69.40 FL
10	1		*FRONT BUMPER INNER AIR DUCT	Not Necessary	59.80 F	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	542.90 F	*- FL
12	1		*FRONT BUMPER BLIND SPORT SENSOR	Damaged	1,800.70 F	*1,800.70 FL
13	1		*FRONT BUMPER TOP GARNISH	Cracked	354.20 F	*354.20 FL
14	1		*FRONT BUMPER TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
15	1		*HEADLAMP LH	Cracked	4,740.30 F	*4,140.30 FL
16	1		*HEADLAMP BRACKET LH	Cracked	58.90 F	*58.90 FL
17	1		*HEADLAMP TOP PANEL LH	Buckled	139.40 F	*139.40 FL
18	1		*FRONT SUPPORT PANEL	Not Necessary	785.20 F	*- FL
19	1		*FRONT LH FENDER	Dented	569.90 F	*569.90 FL
20	1		*FRONT LH FENDER BRACKET	Not Necessary	101.40 F	*- FL
21	1		*FRONT LH FENDER INNER SHIELD	Deformed	198.20 F	*198.20 FL
22	1		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
23	1		*FRONT GRILLE	Cracked	560.30 F	*560.30 FL
24	1		*FRONT GRILLE LOGO	Necessary	58.50 F	*58.50 FL
25	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
26	1		*FRONT GRILLE CHROME MOULDING LH	Cracked	371.20 F	*371.20 FL
27	1		*FRONT LH WHEEL RIM	Cut	1,450.00 FS	*800.00 FS
28	1		*FRONT LH TYRE	Not Necessary	300.00 FS	*- FS
29	1		*FRONT LH LOWER ARM	Bent	323.80 F	*323.80 FL
30	1		*FRONT LH KNUCKLE ARM	Damaged	694.90 F	*452.70 FL
31	1		*FRONT LH WHEEL HUB C/W BEARING	Damaged	577.40 F	*385.00 FL
32	1		*FRONT LH SHOCK ABSORBER	Not Necessary	499.90 F	*- FL
33	1		*FRONT LH FENDER ARC GARNISH	Deformed	249.90 F	*249.90 FL
34	1		*FRONT LH FENDER ARC GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	17,967.50	12,979.50
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	2,405.90
Total Parts (S\$)	17,967.50	10,573.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,200.00	600.00
3	WIRING	New	100.00	30.00
4	TO REMOVE RADIATOR END TO TOP UP COOLANT	New	120.00	0.00
5	TO REMOVE CONDENSER AND TO TOP UP GAS	New	120.00	0.00
6	TO REMOVE FRONT UNDERCARRIAGE	New	380.00	180.00
7	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
8	TO PERFORM DIANOGSTIC TEST	New	200.00	120.00
Gross Labour Cost (S\$)			3,270.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >