

SMT9819L 2020 July

Sin Ya Sin.

Mazda CX30 1888cc

TP China.

Veron.

JM6DM2WTA LO100932

1020.40

Front Bumper Distorted

1794.40 ✓

Front Bumper Clips. New

30(SN) ✓

Front Bumper Side Holder LH. Damaged

64.60 ✓

~~Front Bumper Lower Spoiler~~

Front Bumper Arc Protector LH. Deformed

221.40 ✓

Front Bumper Arc Protector Clips. New

30(SN) ✓

Front Bumper Sensor X102 Damaged

240.20
1 piece $240.2 \times 2 = 480.40$

Front Bumper Day Light. Lt. Crushed

688.10 ✓

Front Bumper Day Light Housing Lt. Damaged

62.40 ✓

Front Bumper Inner Side Cover torn

69.40 ✓

Front Bumper Inner Air Duct. New

59.80 X

Front Bumper Reinforcement. New

542.40 X

Front Bumper Blind Spot Sensor. Damaged

1800.70 ✓

SMT9818L.

Front Bumper Top Garnish	cracked	354.20. ✓
Front Bumper Top Garnish Clips.	new	20(SN). ✓
Handcup L.H.	cracked	4140.30. ✓
Handcup Bracket L.H.	cracked	4740.30. ✓
Handcup Top Panel L.H.	cracked	58.90. ✓
Front Support Panel	new	139.40. ✓
Front LH Fender	Dented	785.20. +.
Front LH Fender Bracket	new	569.90. ✓
Front LH Fender Inner Shield	Debond	101.40. x
Front LH Fender Inner Shield clips.	new	198.20. ✓
Front Grille	cracked	30(SN). ✓
Front Grille Logo	new	560.30. ✓
Front Grille Clips	new	58.50. ✓
Front Grille Chrome Moulding L.H.	cracked	20(SN). ✓
Front LH Wheel Rim.	cut	371.20. ✓
Front LH Tyre.	new	80(SN).
Front LH Lower Arm.	Bent	1450 ✓

SMT9819L

452.70

Front LH Knuckle Arm. Dargid ~~694.90~~ 385

Front LH Wheel Hub c/w Bearly Dargid ~~577.40~~ 499.90 X.

Front LH Shock Absorber Wern

Defend ~~249.90~~ ✓

Front LH Fender Arc Garnish

Front LH Fender Arc Garnish Clips. n 20(SN) ✓

~~1000~~ 600

Panel Beating

~~1200~~ 600

Spring Beating

~~100~~ 30

Wiring.

To remove radiator and to
top up coolant.

120 X

To remove condenser and to
top up gas.

120 X

To remove front underengine.

~~380~~ 180

To perform wheel alignment

~~170~~ 80

To perform diagnostic test.

~~200~~ 120

SMT9819L.

List : 12029.50

less 20% : 9623.60

S.N : 950

Labour : 1610

Total : 12183.60

L/S : 9.7K.

06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: