

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012512/AVP3Q2**Date:** 15/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00263612202
Claimant Vehicle No :	PD8288Z	Insured Vehicle No :	SLJ2348P
Date of Loss:	09/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D208903/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PD8288Z	Engine No:	65195033561516
Make & Model:	MERCEDES-BENZ V220D, 2.1 D LONG (A)	Chassis No:	WDF44781523187939
Reg. Date:	28/09/2016 (Man. Year: 2016)	Odometer:	351142 km
Colour:	Black		
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Wanli 6 mm	Rear Left Side:	Wanli 6 mm
Front Right Side:	Wanli 6 mm	Rear Right Side:	Wanli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,800.70	700.00	2,100.70	75.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	860.00	440.00	33.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,100.70	1,560.00	2,540.70	61.96
Approved Total (Overridden) (S\$)		1,200.00		
Nett Amount (S\$)	4,100.70	1,200.00	2,900.70	70.74

INSPECTION

Date of Assignment:	14/12/2022	Automobile Hub Enterprise 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT Singapore 417883
Date Inspected:	15/12/2022 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 15 May 2023)	
Parts:	N/A	MERCEDES-BENZ V220D 2.1 D LONG (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PD8288Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,638.00 FL	*- FL
2	1		*REAR BUMPER SIDE HOLDER	Not Necessary	85.00 FL	*- FL
3	1		*REAR BUMPERS CLIPS	Not Necessary	50.00 FS	*- FS
4	1		*REAR WHEEL RIM	Cut	1,200.00 FS	*700.00 FS
					Sub Total (\$\$)	2,973.00 700.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	172.30 0.00
					Total Parts (\$\$)	2,800.70 700.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING	New	600.00	550.00
3	WIRING	New	50.00	0.00
4	TO APPLY TUFF COAT	New	100.00	30.00
5	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (S\$)			1,300.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >