ASS. REC. BY:	220125221km /
/	SSIGNMENT
From: Date:	Veh No: SND 98335 Yr Regn: 02, 22
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD /TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Maka: Tu alan wagon
at Workshop m/s 1 teny 7gp Sery	Colour M. Black AC: Insured / Std / NI / NA
at Workshop m/s  I tany Yap Say  of 589  Insured:	Sp.Reading 75811 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	CNO: ZWR80 . 0304435
Stum Incomed	_ Oon. Cond. Good   Fair / Poor / Burnt
(Client's Record)	Steering: Inorder Jammed / Leaked / Burnt or
(Client's Record) lake of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: Nil / S/Rim / STD A/Rim or
Policy Condition)	Tyre Stze: F: Tarroad 193/65R15
mark: The yeb had commerced to	R: GY
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
or Market Value: 8/70k	TOYO/YOKO or
Accident Rport: Consistent? : Yes or No	Front 7 Rear 0
	R/Bal. 7 mm 'R/Bal. 9 mm
-0/	L/Bal. 7 mm L/Bal. 8 mm
	D.O.A. 9/12/22 D.O.I. 19/12/202
20% - 37al 165 of No	Survey held at
REV / REP. / 24 HRS	Des. of Damages : Frt / Rear 7 O/S / N/S / U/C / Rooftop or
Person Contacted: Vehicle: IN / OUT	
Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
/ GIAVESIAN AND	
GIAVENNOT ready	
1/2m 8 15001 Can and	dovo (Pod \$47470.00(070))
1 9 0000 Carw @04	4 days (Red \$17479.90/87%)
+	
	ays Of Repair: 4
Prell. Report Da	ays Of Repair: 4
Prell. Report Da	esurvey No. of Trip: Survey Fee:
Prell. Report Da  I : Final Report Re	Survey Fee: Transportation:
Prell. Report Da	esurvey No. of Trip: Survey Fee:
Prell. Report Da  I : Final Report Re	Survey No. of Trip:  Survey Fee:  Transportation:  Site Insp (\$ )S - RSSI
Prell. Report Da	Survey No. of Trip:  Survey Fee:  Transportation:  Site Insp (\$ ) _ \$ + R\$ _ \$I  Interview (\$ ) Finals
Preli. Report Da  I : Final Report Re  I : TP	Survey No. of Trip:  Survey Fee:  Transportation:  Site Insp (\$ )_\$-RS_\$!  Interview (\$ ) Finis  Tech Invs (\$ ) Others
Prell. Report Da	Survey No. of Trip:  Survey Fee:  Transportation:  Site Insp (\$ ) _ \$ + R\$ _ \$I  Interview (\$ ) Finals

Not Nothern Ulby 82500h Bearry After Paint 15722 4days

## AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-01 Sin Ming AutoCity, Singapore 575722 Tel: 6266 9511 Fax: 6266 9512

Vehicle No /ehicle Model :

SND9833S

TOYOTA NOAH HYBRID 1.8X CVT

Date: 22/12/2022

## **Estimate Repair Cost**

Qt	y Parts List Items	
1		By 891.60
2		\$5m 95.60 K
2	Rear bumper brackets	5 A 98.90 K
2	Rear bumper reflectors	5/cc 92.90 X
2	Rear bumper tow cover	\$ 1 48.90 ₺
1 se		5 th 40.00
1	Rear tailgate	A \$ 1,561.90 —
1	Rear tailgate centre logo	\$ 68.90 X
1	Rear tailgate outer chrome handle	5 769.50 X
1	Rear tailgate lock	\$ N 771.80 K
2	Rear tailgate hinges	\$ 129.60 X
2	Rear tailgate dampers	\$/m 419.50 X
2	Rear tailgate weatherstrip	\$10 471.60 X
1	Rear tailgate number plate lamp	\$ 1 98.70 \$
1	Rear tailgate inner top garnish	\$52.90 /
2	Rear tailgate inner side garnish	\$/h 783.60 K
1	Rear tailgate inner trim board	\$4 619.60 X
2	Tail lamps	In \$ 1,973.80 ⊀
2	Rear fender inner side trims	₹ \$ 1,979.80 X
1	Rear end panel .	\$# 918.00 X
1	Rear end pannel top garnish	14 \$ 352.90 x
1	Rear spare tyre compartment	
1 1	Rear spare tyre top board	
A 100 PM		A STATE OF THE PARTY OF THE PAR
	12/	\$ 14,989.90
	Parts Special Nett Items	0
1	Rear number plate	\$ 10.00 X
20	Reverse sensor	\$1n 300.00 X
1	Reverse camera	\$ 1 250.00 1
		\$ 610.00
	LKK Auto Consultants hence notify the Repairer of the following: Total Parts  To resurvey before/aiver spray pointing	\$ 15,599.90

- To display damaged partis; during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- · Supplementar, i.e. vs. in it he resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Cate:

## Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts	\$	1,800.00	5001
2	To putty and respary paintig on affected areas.	\$	1,500.00	600
3	To remove, replace rear tailgate fittings to facilitate repair.	\$	300.00	115
4	To remove, replace rear windscreen glass.	\$	200.00	1201
5	To remove, replace reverse camera.	us,	150.00	X
6	To remove, replace reverse sensor.	\$	150.00	5d
7	To remove, replace rear exhausr silencer.	in s	200.00	×
8	To check wiring and lightings.	\$		201
	Total Labour	\$	4,380.00	
	Total Parts and Labour	\$	19,979.90	