Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

Our reference:

22 - 171030

Date:

24/11/2022

c/o Garage 13 Pte Ltd 8 Kaki Bukit Ave 4 #03-46 Premier@KB Singapore 415875

Dear Sirs

RE:

Road Traffic Accident on 05-02-2022

Siang Hock Car Rental Pte Ltd

In accordance with your instructions received in this office on

10-10-2022

, we made arrangements to

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800

Hotline: 6385 1171

examine the vehicle on

10-10-2022

at above-mentioned address. The following data was

recorded:

#### Vehicle details


Make	Nissan	Registration	GBJ8440J
Model	NV350 PANEL VAN 5DR 2.5 5AT	R 2.5 5AT Chassis JN1MC2E26Z00314	
Colour	White	Gearbox	Auto
Odometer	75636km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

### Tyre Depths

Front left	195R15LT	80% Black Arrow		
Front right	195R15LT	80% Black Arrow		
Rear left	195R15LT	80% Stitch		
Rear right	195R15LT	80% Double King		

Status	REPAIRABLE		
Magnitude	Medium		
Legal status	Unroadworthy		

Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$2,200.00 and 3 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis:

• Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd www.iaconsultingsg.com

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

22 - 171030

Date

24/11/2022

Page

2

### Section A: Damaged Parts Assessment

Section	ni Damagea	i di to / toocooniciit			
Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment	
List Items :					
Front bumper	1	holder broken.torn	921.10	921.10	Br 620
Front bumper fog lamp cover rh	1	cracked	125.00	125.00	csal
Front bumper side retainer rh	1	cracked	112.00	112.00	(19 3
Front door step garnish rh	1	not necessary	144.00	0.00	XIUN
Front corner panel rh - slightly dented	1	repair.respray	268.00	0.00	SCRXP
Headlamp @\$833.60	2	rh broken Ih check.refix	1667.20	833.60	cra400
Headlamp panel rh - slightly dented	1	repair.respray	146.88	0.00	XNN
	Sub- To	otal cost	3384.18	1991.70	1257
Perce	entage discount :	10%	338.42	199.17	125.70
	Sub-Total co	osts for parts	3045.76	1792.53	1131.3
Special Nett Items:					
Front bumper clips	set	necessary	50.00	50.00	/nec
	Sub-Total co	osts for parts	50.00	50.00	50
Parts Repair					
		12	0.00	0.00	
	Sub- To	tal costs	0.00	0.00	
	Total cost	rs for parts	3095.76	1842.53	11212

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171** 

Our reference:

22 - 171030

Date

24/11/2022

Page

3

### Section B: Labour Cost Calculation

	Hourly rat	e Manhr. Req.	Total	
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.		10	\$	450.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$	450.00
Apply rust proofing on the adjacent panels.	Sub-co	\$	30.00	
Wiring / bulb checking (inclusive of re-focus / re-adjust on angle of light intensity.)	\$ 45.00	0.8	\$	36.00
	Total	labour cost	\$	966.00

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's 630 operating cost and in-house@ IA Research Guidelines respectively.

Practicing Management Consultant (PMC) of SBACC Approved Training Organisation (ATO) of Workforce Singapore #06-46 Synergy @KB Singapore 417800

No.25 Kaki Bukit Road 4

Hotline: 6385 1171

Our reference:

22 - 171030

Date

24/11/2022

### Section C: Summary Table of Total Repair Cost

Desc	ription	Cost	
Damaged Parts Assessment (See section A)		\$1,842.53	1181.30
Labour Cost Calculation (See section B)		\$966.00	630
Total cost		\$2,808.53	1811.30
Lump Sum		ĆECA 74	362.26
Further discount	20%	\$561.71	362.20
Total Repair Cost		\$2,200.00	1449.04

We would recommend a sum of

\$2,200.00

and

working days for repair.

15/12/22 11fon

~1450M

No further items will be approved without our expressed written agreement. Any significant additional

items will be subject to a supplementary report.

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma. Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

Enterprise Singapore - Recognised Certification for Management Consultants

IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)

Subsidiaries of Impact Analysis:

• Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd www.iaconsultingsg.com