

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/GRB21008500/TVY3E2-1**Date:** 12/01/2023REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	FBS929Y	Insured Vehicle No :	SLK8639E
Date of Loss:	04/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003332

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBS929Y	Engine No:	G3L8E0208116
Make & Model:	YAMAHA NMAX155, 155cc ABS CVT	Chassis No:	MH3SG5680LK030826
Reg. Date:	09/01/2021 (Man. Year: 2020)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70 R13	Rear Tyre Size:	130/70 R13
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,460.95	4,702.35	2,758.60	36.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	900.00	750.00	45.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,110.95	5,602.35	3,508.60	38.51
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	9,110.95	4,500.00	4,610.95	50.61

INSPECTION

Date of Assignment:	13/08/2021	Lkt Group Pte Ltd (HQ)
Date Inspected:	13/08/2021 Inspected At:	Blk 3006 Ubi Road 1, #01 - 384 Kampong Ubi Industrial Estate
Estimated Period of Repair:	5.0 days	Singapore 408700

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Jan 2023)	
Parts:	N/A	YAMAHA NMAX155 155cc ABS CVT (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBS929Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT INNER FENDER	Distorted	99.46 F	*99.46 FL
2	1		*FRONT WHEEL AXLE	Bent	20.50 F	*20.50 FL
3	1		*FRONT BRAKE DISC	Not Necessary	169.30 F	*- FL
4	2		*FRONT FORK	Bent	1,828.48 F	*980.00 FL
5	1		*FRONT FORK UNDER BRACKET	Distorted	559.20 F	*559.20 FL
6	1		*FRONT FORK CLAMP	Distorted	105.10 F	*105.10 FL
7	1		*STEERING STEM	Bent	582.00 F	*582.00 FL
8	1		*SET STEERING CONE BEARING ASSY	Necessary	189.80 F	*189.80 FL
9	1		*HANDLE BAR	Bent	194.20 F	*194.20 FL
10	1		*HANDLE BAR BRACKET	Distorted	92.50 F	*92.50 FL
11	2		*HANDLE BAR HOLDER LOWER	Distorted	54.80 F	*54.80 FL
12	2		*HANDLE BAR HOLDER UPPER	Distorted	51.00 F	*51.00 FL
13	1		*SET HANDLE GRIP	Cut	110.00 F	*110.00 FL
14	1		*SET HANDLE BAR BALANCER	Missing	55.00 F	*55.00 FL
15	1		*SET SIDE MIRROR	Twisted	96.20 F	*96.20 FL
16	1		*REAR BRAKE LEVER	Bent	84.70 F	*84.70 FL
17	2		*FRONT SIDE TOP FAIRING	Deep Grazed	376.40 F	*376.40 FL
18	1		*FRONT SIDE CENTRE FAIRING N/S	Cut	145.60 F	*145.60 FL
19	1		*FRONT SIDE CENTRE FAIRING LOGO N/S	Necessary	35.00 F	*35.00 FL
20	1		*FRONT SIDE LOWER FAIRING N/S	Distorted	177.25 F	*177.25 FL
21	1		*SIGNAL LAMP N/S	Cracked	87.36 F	*87.36 FL
22	1		*FLOORBOARD PANEL N/S	Distorted	216.80 F	*216.80 FL
23	1		*SIDE STAND	Bent	80.00 F	*80.00 FL
24	1		*MAIN STAND	Bent	165.30 F	*165.30 FL
25	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
26	1		*FRONT FENDER CARBON FIBRE (ACCESSORIES)	Cut	335.00 FS	*200.00 FS
27	1		*SET FLOORBOARD PANEL ALUMINIUM (ACCESSORIES)	Not Necessary	140.00 FS	*- FS
28	1		*FRONT TYRE R13	Not Necessary	150.00 FS	*- FS
29	1		*SET FORK SEAL	Necessary	60.00 FS	*50.00 FS
30	1		*FORK OIL	Necessary	50.00 FS	*40.00 FS
31	1		*REAR CARRIARE BOX	Deep Grazed	280.00 FS	*280.00 FS
32	1		*FRONT CAST WHEEL RIM R13	Repair	820.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,460.95	5,158.17
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	455.82
Total Parts (\$\$)	7,460.95	4,702.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT BODY FRAME ALIGNMENT	New	350.00	0.00
2	TO REMOVE / REPLACE DAMAGED PARTS & COMPONENTS	New	700.00	450.00
3	TO RESPRAY REPLACED & AFFECTED PARTS	New	600.00	450.00
Gross Labour Cost (\$\$)			1,650.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >