



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 3904J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	485.00	-
2	FRONT FENDER UNDERSHIELD LH	CRACKED	298.00	112.00
1	FRONT FENDER VVTI EMBLEM LH	NOT NECESSARY	68.00	-
1	FRONT BUMPER	CRACKED	598.00	525.00
1	FRONT BUMPER SIDE RETAINER LH	DISTORTED	186.00	92.00
1	HEADLAMP LH	MTG DISTORTED	680.00	405.00
1	HEADLAMP LOWER BRACKET LH	TO REPAIR SEE LABOUR	146.00	-
	LESS 15% DISCOUNT		-369.15	-170.10
			2,091.85	963.90
LABOUR				
	LABOUR CHARGES TO REPLACE REPAIR ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH AND HEADLAMP LOWER BRACKET LH.		800.00	250.00
	TO DO ANTI-RUST.	NOT NECESSARY	60.00	-
	CHECK WIRING SYSTEM, FORCUS HEADLAMP.		90.00	20.00
	TO DO SPRAY PAINTING.		800.00	220.00
			1,750.00	490.00
GRAND TOTAL			3,841.85	1,453.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,150.00

Report Ref No. CS/LIP22012528/Kwy3e2

MARKET VALUE: \$52,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$16,679.00=NETT VALUE: \$35,321.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.