

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933
Reg : 201838521G

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLH 1233 D**
MODEL : **TOYOTA HARRIER**
DATE OF ACCIDENT : 11.12.2022
CHASSIS : ZSU600087479
DATE OF REG : 25.10.2016

xiao long

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE	1	\$ 1,548.20	\$ 1,548.20
2	TAILGATE LAMP	1	\$ 498.50	\$ 498.50
3	TAILGATE LAMP INNER SEALER	1	\$ 38.00	\$ 38.00
4	TAILGATE EMBLEM 'HARRIER'	1	\$ 98.20	\$ 98.20
5	TAILGATE INNER LOCK	1	\$ 954.40	\$ 954.40
6	TAILGATE LOCK BOTTOM (OUTER)	1	\$ 50.00	\$ 50.00
7	TAILGATE WEATHER STRIP	1	\$ 353.40	\$ 353.40
8	TAILGATE STOPPER	2	\$ 25.70	\$ 51.40
9	TAILGATE INNER TRIM (LOWER)	1	\$ 468.20	\$ 468.20
10	TAILGATE WINDSCREEN MOULDING	1	\$ 218.50	\$ 218.50
11	REAR BUMPER (UPPER) JAPAN MODEL	1	\$ 1,770.93	\$ 1,770.93
12	REAR BUMPER (LOWER)	1	\$ 495.60	\$ 495.60
13	REAR BUMPER REFLECTOR	1	\$ 92.60	\$ 92.60
14	REAR BUMPER CORNER RETAINER	1	\$ 98.20	\$ 98.20
15	REAR BUMPER SIDE RETAINER	1	\$ 89.60	\$ 89.60
16	REAR BUMPER SPONGE	1	\$ 298.20	\$ 298.20
17	TAIL LAMP	1	\$ 585.60	\$ 585.60
18	TAIL LAMP PANEL	1	\$ 286.90	\$ 286.90
19	REAR FENDER	1	\$ 1,405.80	\$ 1,405.80
20	REAR FENDER QUARTER GLASS WITH MOLDING	1	\$ 398.70	\$ 398.70
21	REAR FENDER INNER COWLING	1	\$ 168.90	\$ 168.90
22	REAR FENDER INNER TRIM	1	\$ 573.80	\$ 573.80
23	REAR RIM	1	\$ 1,085.90	\$ 1,085.90
24	REAR END PANEL	1	\$ 785.60	\$ 785.60
25	REAR END PANEL TOP GARNISH	1	\$ 343.40	\$ 343.40
26	REAR END PANEL DAMPER	1	\$ 1,395.20	\$ 1,395.20
27	REAR END PANEL DAMPER BRACKET	2	\$ 275.80	\$ 551.60
28	REAR STORAGE COMPARTMENT GARNISH	1	\$ 687.50	\$ 687.50

5693.30
4269.97

TOTAL PRICE	\$ 15,392.83
LESS 25%	\$ 3,848.21
SUB TOTAL PRICE	\$ 11,544.62

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE WITH CASING <i>Not new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER (UPPER) CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER (LOWER) CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
4	TAIL GATE APRON GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
5	TAILGATE INNER TRIM (LOWER) CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
6	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 100.00	\$ 100.00
7	TAILGATE WINDSCREEN INNER SHIELD <i>new</i>	1	\$ 60.00	\$ 60.00
8	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
9	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
10	REAR FENDER STOPPER <i>new</i>	1	\$ 35.00	\$ 35.00
11	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
12	REAR FENDER QUARTER GLASS SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
13	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
14	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00
15	REVERSE SENSOR (SET) <i>Not new</i>	1	\$ 300.00	\$ 300.00

170

TOTAL \$ 1,015.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,000.00	900
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	900
3	TUFF COAT	\$ 250.00	80
4	WIRING AND BULB CHECK	\$ 100.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	80
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	+
8	TRANSFER TAILGATE MECHANISM	\$ 120.00	+
9	CONDUCT WATER LEAKAGE TEST	\$ 120.00	+
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	+
11	REMOVE AND REFIT FENDER QUARTER GLASS	\$ 120.00	60

13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL

5280

2050

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,559.62
TOTAL LABOUR COST : \$ 5,280.00
TOTAL REPAIR COST : \$ 17,839.62

Adrian Cj

H/s 15/12/22

07 Days .

total : 6 489.97

c/s: 5.21k

5.21k

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: