

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

**Our File No:** CS6/AIS22012540/CVY3M4**Date:** 29/12/2022**REFERENCE**

Insured/Claimant: Runjeet Singh S/O Mukhtar Singh Policy No: SP2000756192-01  
Date of Loss: 11/12/2022 Nature of Claim: OD Claim No: 202222008810

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLR8450U**  
Make & Model: NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A) Engine No: HR15285304B  
Reg. Date: 08/01/2010 (Man. Year: 2009) Chassis No: JN1BAAG11Z0110642  
Colour: White Odometer: 180089 km  
Engine Capacity: 1498 cc  
Market Value/New Car Price: S\$23,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: Firenza 4 mm Rear Left Side: Firenza 4 mm  
Front Right Side: Firenza 4 mm Rear Right Side: Firenza 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,834.20	1,690.20	1,144.00	40.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	530.00	350.00	39.77
Paintwork Labour	900.00	600.00	300.00	33.33
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,614.20</b>	<b>2,820.20</b>	<b>1,794.00</b>	<b>38.88</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,250.00</b>		
<b>- Excess (S\$)</b>	500.00	500.00	0.00	0.00
<b>(S\$)</b>	4,114.20	1,750.00	2,364.20	57.46
<b>+ GST 7.00/7.00% (S\$)</b>	287.99	122.50	165.49	57.46
<b>Nett Amount (S\$)</b>	<b>4,402.19</b>	<b>1,872.50</b>	<b>2,529.69</b>	<b>57.46</b>

**INSPECTION**

Date of Assignment: 14/12/2022 Present Location: Success United Pte Ltd (HQ)  
Date Inspected: 14/12/2022 Inspected At: Success United Pte Ltd (HQ)  
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub  
Singapore 417921  
Estimated Period of Repair: 5.0 days

**Adjuster:** SIMON HO LEONG CHUAN**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Dec 2022)
<b>Parts:</b>	143	NISSAN SYLPHY 1.5 4AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLR8450U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*FRT BUMPER ASSY</b> (WCP)	Dented	350.00 F	*350.00 F
2	1		<b>*FRT BUMPER CLIPS</b>	Necessary	30.00 FS	*30.00 FS
3	1		<b>*FRT BUMPER SIDE HOLDER L/RH</b> (2PCS) (WCP)	N/s Cracked/ O/s Not Necessary	60.00 F	*30.00 F
4	1		<b>*FRT BUMPER BRACKET LH</b> (WCP)	Cracked	85.00 F	*85.00 F
5	1		<b>*FRT BUMPER CHROME TRIM</b> (WCP)	Cut	35.00 F	*35.00 F
6	1		<b>*FRT BUMPER FOGLAMP COVER LH</b> (WCP)	Cracked	42.00 F	*42.00 F
7	1		<b>*FRT BUMPER FOGLAMP ASSY LH</b> (WCP)	Cracked	180.00 F	*180.00 F
8	1		<b>*FRT BUMPER LOWER AIR GRILLE</b> (WCP)	Not Necessary	70.00 F	*- F
9	1		<b>*FRT BUMPER INNER SPONGE</b> (WCP)	Cracked	150.00 F	*150.00 F
10	1		<b>*FRT BUMPER REINFORCEMENT</b> (WCP)	Not Necessary	200.00 F	*- F
11	1		<b>*FRT HEADLAMP ASSY LH</b> (WCP)	Cut	325.00 F	*325.00 F
12	1		<b>*FRT GRILLE ASSY</b> (WCP)	Cracked	165.00 F	*165.00 F
13	1		<b>*FRT BONNET</b> (WCP)	Repair	490.00 F	*- F
14	1		<b>*FRT BONNET MECHANISM LOCK</b> (WCP)	Serviceable	70.00 F	*- F
15	1		<b>*RADIATOR SUPPORT PANEL ASSY</b> (WCP)	Repair	180.00 F	*- F
16	1		<b>*RADIATOR SUPPORT PANEL TOP LOWER GARNISH</b> (WCP)	Distorted	120.00 F	*120.00 F
17	1		<b>*RADIATOR SUPPORT PANEL TOP LOWER GARNISH CLIPS</b>	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

<b>Sub Total (\$)</b>	<b>2,582.00</b>	<b>1,542.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$)</b>	252.20	148.20
<b>Total Parts (\$)</b>	<b>2,834.20</b>	<b>1,690.20</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Paintwork Labour</u></b>				
1	To putty and respray painting on bonnet, bumper, fender LH and support panel	New	900.00	600.00
<b><u>Labour Items</u></b>				
2	To remove, repair and replaced damaged bodyparts, realigned bodyworks & where consistent to the accident	New	800.00	500.00
3	To remove, rearrange electrical wiring,check lighting	New	80.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>1,780.00</b>	<b>1,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >