

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 5982M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT O/S FENDER	TO REPAIR SEE LABOUR	588.00	-
1	FRONT O/S FENDER INNER SHIELD	SERVICEABLE	107.00	-
8	FRONT O/S FENDER INNER SHIELD CLIPS @\$3.50	NOT NECESSARY	28.00	-
1	FRONT BUMPER	CUT	985.00	985.00
10	FRONT BUMPER CLIPS @\$3.50	NECESSARY	35.00	35.00
1	FRONT BUMPER O/S SIDE RETAINER	NOT NECESSARY	28.00	-
1	FRONT BUMPER O/S SIDE BRACKET CLIPS	NOT NECESSARY	5.50	-
1	FRONT BUMPER O/S FOG LAMP ASSY	NOT NECESSARY	426.00	-
1	O/S HEAD LAMP ASSY	CUT / MTG BROKEN	698.00	698.00
1	O/S HEAD LAMP LOWER RETAINER	NOT NECESSARY	22.00	-
	LESS 10% DISCOUNT		-292.25	-171.80
			2,630.25	1,546.20
	<u>LABOUR</u>			
	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT.		50.00	30.00
	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING.	NOT NECESSARY	150.00	-
	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT FRONT SUPPORT PANEL, HEAD LAMP PANEL & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT O/S FENDER.		800.00	550.00
	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.		950.00	600.00
	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS.		60.00	30.00
			2,010.00	1,210.00
	GRAND TOTAL		4,640.25	2,756.20

Report Ref No. CS/SMR22012545/Dny3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,200.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/SMR22012545/Dny3e2



**Automotive Assessor / Investigator**