

Date: 13/12/2022

Vehicle No: SMP8130S

Model: HONDA FIT HYBIRD 1.5

Chassis: GP51336705 - 2018

Reg.Year: 2019

*Not Authorized
C/Ping @
Meaning After Rainy
4 days*

Third Party Insurer: AIG

Third Party Veh No: SKT1295Z

Date of Accident: 11/12/2022

Estimator: KIT

Surveyor:

ESTIMATE

| NO. | DESCRIPTION | QTY | UNIT S\$ | AMOUNT S\$ |
|-------------|-----------------------------------|-----|----------|------------------------|
| 1 | REAR TAILGATE | 1 | | <i>Pr</i> \$1,052.50 ✓ |
| 2 | REAR TAILGATE WINDSCREEN MOULDING | 1 | | <i>Mu</i> \$157.30 ✓ |
| 3 | REAR TAILGATE "FIT" EMBLEM | 1 | | <i>Mu</i> \$48.80 ✓ |
| 4 | REAR TAILGATE "HYBRID" EMBLEM | 1 | | <i>Mu</i> \$47.50 ✓ |
| 5 | REAR TAILGATE MECHANISM LOCK | 1 | | <i>r</i> \$150.80 X |
| 6 | REAR TAILGATE WEATHERSTRIP | 1 | | <i>Pr</i> \$112.30 X |
| 7 | REAR BUMPER | 1 | | <i>BUC</i> \$753.10 ✓ |
| 8 | REAR END PANEL TOP GARNISH | 1 | | <i>Pr</i> \$112.10 X |
| 9 | REAR END PANEL | 1 | | REPAIR |
| SUB TOTAL | | | | \$2,434.40 |
| LESS 20% | | | | -\$486.88 |
| PARTS TOTAL | | | | \$1,947.52 |

| NO. | SPECIAL NETT | QTY | UNIT S\$ | AMOUNT S\$ |
|-----------|----------------------------------|-----|----------|---------------------------------|
| 1 | REAR TAILGATE WINDSCREEN SEALANT | 1 | | <i>Mu</i> \$60.00 <i>Gain</i> ✓ |
| 2 | REAR BUMPER CLIPS | 1 | | <i>Mu</i> \$50.00 ✓ |
| 3 | REAR BUMPER REVERSE SENSOR | 1 | | \$250.00 ? |
| 4 | REAR END PANEL TOP GARNISH CLIPS | 1 | | <i>Mu</i> \$30.00 X |
| S/N TOTAL | | | | \$390.00 |

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 13/12/2022
 Vehicle No: SMP8130S
 Model: HONDA FIT HYBIRD 1.5
 Chassis: GP51336705 - 2018
 Reg.Year: 2019

Third Party Insurer: AIG
 Third Party Veh No: SKT1295Z
 Date of Accident: 11/12/2022
 Estimator: KIT
 Surveyor:

LABOUR CHARGES:

| | | |
|--|---------------------|-------------------|
| LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST AT ACCIDENT AREA. | \$600.00 | <i>400</i> |
| LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREA. | \$600.00 | <i>400</i> |
| LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS & ETC. | \$120.00 | ✓ |
| LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS. | \$100.00 | <i>60</i> |
| LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. | \$100.00 | <i>50</i> |
| TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. | \$80.00 | <i>15</i> |
| | LABOUR TOTAL | \$1,600.00 |
| KIT | TOTAL | \$3,937.52 |