



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 2342G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
2	FRONT FORK	DENTED / BENT	580.00	580.00
1	UNDER BRACKET	DENTED	102.00	102.00
1	STEERING CONE W/BEARING	CRACKED	186.00	186.00
1	FRONT MUDGUARD	SLICED	185.00	185.00
1	FRONT WHEEL RIM	DENTED / WARPED	585.00	585.00
1	FRONT WHEEL SCREW	BENT	25.00	25.00
1	HEADLAMP	SERVICEABLE	325.00	-
1	HEADLAMP COWLING	SLICED	168.00	168.00
1	HANDLE BAR	DENTED / BENT	195.00	195.00
2	HANDLE GRIP	NECESSARY	84.00	84.00
2	HANDLE BALANCER	SLICED	76.00	76.00
1	L/H FRONT SIGNAL LAMP	SLICED	85.00	85.00
1	BRAKE LEVER	SLICED	85.00	85.00
1	CLUTCH LEVER	FRACTURED	85.00	85.00
2	MIRROR	SLICED	136.00	136.00
1	SPEEDOMETER	NOT NECESSARY	592.00	-
1	FUEL TANK	TO REPAIR SEE LABOUR	689.00	-
1	L/H FUEL TANK SIDE COVER	SLICED	132.00	132.00
1	L/H FUEL TANK LOWER COVER	SLICED	95.00	95.00
1	R/H FUEL TANK SIDE COVER	SLICED	132.00	132.00
1	R/H FUEL TANK LOWER COVER	CRACKED	95.00	95.00
1	R/H FRONT FOOT REST	SLICED	72.00	72.00
1	R/H REAR FOOT REST	SLICED	72.00	72.00
1	L/H FRONT FOOT REST	SLICED	72.00	72.00
1	L/H REAR FOOT REST	SLICED	72.00	72.00
1	GEAR PEDAL	BENT	82.00	82.00
1	EXHAUST MUFFLER	NOT NECESSARY	580.00	-
1	EXHAUST MUFFLER COVER	SLICED	95.00	95.00
1	REAR WHEEL RIM	SERVICEABLE	580.00	-
1	CUSHION SEAT	CUT	320.00	320.00

Report Ref No. CS3/SMR22008142/Gny3e2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-	-381.60
			6,582.00	3,434.40
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	DENTED	28.00	22.00
1	FRONT TYRE (SN)	NOT NECESSARY	250.00	-
1	REAR BOX (SN)	SLICED	250.00	180.00
1	REAR BOX BRACKET (SN)	DENTED / BENT	200.00	160.00
1	IU UNIT (SN)	SLICED	160.00	156.00
			888.00	518.00
	<b><u>LABOUR</u></b>			
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF FUEL TANK.		650.00	350.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		400.00	300.00
	TO ALIGN MAIN BODY FRAME.		300.00	150.00
	TRANSPORTATION CHARGES.		70.00	50.00
			1,420.00	850.00
<b>GRAND TOTAL</b>			<b>8,890.00</b>	<b>4,802.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,850.00</b>

Report Ref No. CS3/SMR22008142/Gny3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.