5/2/23, 1:37 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22012566/RWP3Q2

02/05/2023 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00048752201

Claimant Vehicle

SGA5554Y

Insured

GBJ4330U

Odometer:

No:

Vehicle No:

Date of Loss:

20/10/2022

Nature of Claim: TP

Claim No:

39434 km

SNM22D207707/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

SGA5554Y Reg No:

90513011N74B66B Make & Model: BMW 760LI, 6.0 (A) Engine No: Reg. Date: 26/06/2018 (Man. Year: 2018) Chassis No: WBA7H62080BL02290

Colour: Black

Engine Capacity: Market Value/New Car

Sum Insured (S\$):

N/A

Price:

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

6592 cc

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R20 245/40Z R20 Rear Tyre Size: Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,297.05	40.00	10,257.05	99.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,188.00	1,903.00	3,285.00	63.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,485.05	1,943.00	13,542.05	87.45
+ GST 8.00/8.00% (S\$)	1,238.80	155.44	1,083.36	87.45
Nett Amount (S\$)	16,723.85	2,098.44	14,625.41	87.45

INSPECTION

Date Inspected:

Date of Assignment: 15/12/2022

Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby Performance 06/03/2023 Inspected At:

Centre

Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/2/23, 1:37 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 May 2023)

Parts: BMW 760LI 6.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGA5554Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*40.00 FS
2	1		*ALLOY RIM 8.5JX20 DOUBLE SPK 760M	Not Necessary	2,075.65 FS	*-FS
3	1		*ACTIVE STABI	Not Necessary	4,570.20 FS	*- FS
4	1		*(S/L) FRT RH AIR SPRING STRUT	Not Necessary	3,571.20 FS	*-FS
F=Fra	anchise	part. S=SpcN	lett.	Total Parts (S\$)	10,297.05	40.00
			Report was unsubmitted duri	ng this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO MAKE GOOD FRONT RIGHT FENDER AND FRONT BUMPER	New	1,770.00	850.00
2	TO RESPRAY FRONT RIGHT FENDER ,FRONT BUMPER AND AFFECTED AREAS	New	1,923.00	885.00
3	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	531.00	0.00
4	TO REPLACE WHEEL RIM INCLUDING BALANCING	New	94.00	0.00
5	TO REPLACE FRONT RIGHT PNEUMATIC SPRING STRUT INCLUDING RESET AND CHECK FUNCTION OF RIDE LEVEL HEIGHT CONTROL FOR PROPER FUNCTION	New	516.00	0.00
6	TO CHECK ELECTRICAL	New	177.00	168.00
7	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	0.00
	Gross Labour	Cost (S\$)	5,188.00	1,903.00
	Report was unsubmitted during this p	orint-out.		

< END OF ESTIMATES >