

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012569/UNP3Q2**Date:** 28/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSW00061642200
Claimant Vehicle No :	SMM7462G	Insured Vehicle No :	YQ3970U
Date of Loss:	13/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D209005/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM7462G	Engine No:	G4FGKU171888
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHD841CMKU935615
Reg. Date:	12/07/2019 (Man. Year: 2019)	Odometer:	137989 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,403.20	5,747.28	10,655.92	64.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,490.00	2,080.00	4,410.00	67.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,893.20	7,827.28	15,065.92	65.81
Approved Total (Overridden) (S\$)		6,200.00		
(S\$)	22,893.20	6,200.00	16,693.20	72.92
+ GST 7.00/7.00% (S\$)	1,602.52	434.00	1,168.52	72.92
Nett Amount (S\$)	24,495.72	6,634.00	17,861.72	72.92

INSPECTION

Date of Assignment:	15/12/2022	
Date Inspected:	19/12/2022 Inspected At:	Automobile Integrated Management Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing) Singapore 415933
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM7462G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR LH	Badly Dented	1,912.30 FL	*1,912.30 FL
2	1	*FRONT DOOR OUTER HANDLE LH	Serviceable	168.00 FL	*- FL
3	2	*FRONT DOOR HINGE LH	Not Necessary	112.60 FL	*- FL
4	1	*FRONT DOOR CHECKER LH	Not Necessary	49.60 FL	*- FL
5	1	*FRONT DOOR GLASS CHANNEL LH	Not Necessary	131.00 FL	*- FL
6	1	*FRONT DOOR OUTER MOULDING LH	Not Necessary	59.80 FL	*- FL
7	1	*FRONT DOOR GLASS FRAME BLACK STICKER LH	Necessary	107.00 FL	*107.00 FL
8	1	*FRONT DOOR WEATHERSTRIP LH	Necessary	125.80 FL	*125.80 FL
9	1	*FRONT DOOR INNER LOCK LH	Shorted / Damaged	192.00 FL	*192.00 FL
10	1	*FRONT DOOR FRAME WEATHERSTRIP LH	Repeated	113.00 FL	*- FL
11	1	*FRONT DOOR LOCK CATCH LH	Not Necessary	26.30 FL	*- FL
12	1	*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	745.80 FL	*- FL
13	1	*FRONT DOOR OUTER LOCK BUTTON LH	Not Necessary	185.30 FL	*- FL
14	1	*FRONT DOOR STOPPER (OUTER)LH	Not Necessary	14.00 FL	*- FL
15	1	*SIDE MIRROR ASSY LH	Not Necessary	798.60 FL	*- FL
16	1	*ROCKER PANEL LH	Repair	1,802.60 FL	*- FL
17	1	*CENTER PILLAR LH (OUTER)	Repair	1,458.30 FL	*- FL
18	1	*CENTER PILLAR LH (INNER)	Not Necessary	785.90 FL	*- FL
19	1	*CENTER PILLAR INNER GARNISH (LOWER) LH	Not Necessary	158.20 FL	*- FL
20	1	*REAR DOOR LH	Badly Dented	1,879.20 FL	*1,879.20 FL
21	2	*REAR DOOR HINGE LH	Not Necessary	112.60 FL	*- FL
22	1	*REAR DOOR CHECKER LH	Not Necessary	49.20 FL	*- FL
23	1	*REAR DOOR WEATHERSTRIP LH (DOOR)	Necessary	135.80 FL	*135.80 FL
24	1	*REAR DOOR WEATHERSTRIP LH (FRAME)	Necessary	139.70 FL	*139.70 FL
25	1	*REAR DOOR LOCK CATCH LH	Not Necessary	20.00 FL	*- FL
26	1	*REAR DOOR SPEAKER LH	Not Necessary	125.80 FL	*- FL
27	1	*REAR DOOR INNER LOCK LH	Shorted / Damaged	192.00 FL	*192.00 FL
28	1	*REAR DOOR GLASS REGULATOR GEAR MOTOR LH	Not Necessary	185.60 FL	*- FL
29	1	*REAR DOOR GLASS FRAME BLACK STICKER LH	Necessary	118.90 FL	*118.90 FL
30	1	*REAR DOOR GLASS FRAME GARNISH LH	Not Necessary	54.00 FL	*- FL
31	1	*REAR DOOR OUTER MOULDING LH	Not Necessary	86.00 FL	*- FL
32	1	*REAR DOOR GLASS CHANNEL LH	Not Necessary	85.60 FL	*- FL
33	1	*REAR DOOR INNER TRIM BOARD LH	Not Necessary	645.70 FL	*- FL
34	1	*REAR DOOR OUTER HANDLE LH	Not Necessary	168.90 FL	*- FL
35	1	*REAR DOOR POWER WINDOW HOLDER BOARD LH	Not Necessary	235.60 FL	*- FL
36	1	*REAR WHEEL RIM LH	Warped	925.60 FL	*600.00 FL
37	1	*REAR AXLE	Not Necessary	1,189.00 FL	*- FL
38	1	*REAR SHOCK ABSORBER LH	Not Necessary	298.50 FL	*- FL
39	1	*REAR WHEEL HUP BEARING LH	Damaged	456.30 FL	*456.30 FL
40	1	*REAR BUMPER	Cut	654.80 FL	*484.00 FL
41	1	*REAR BUMPER SIDE RETAINER	Necessary	65.30 FL	*65.30 FL
42	1	*REAR QUARTER PANEL N/S	Badly Dented	1,845.30 FL	*645.00 FL
43	1	*REAR FENDER INNER COWLING LH	Not Necessary	165.30 FL	*- FL
44	1	*REAR FENDER INNER TRIM LH	Not Necessary	569.20 FL	*- FL
45	1	*REAR MUDFLAP LH	Grazed	68.30 FL	*68.30 FL
46	1	*REAR FUEL CAP COVER	Not Necessary	98.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET FRONT DOOR TRIM BOARD CLIP	Not Necessary	50.00 FS	*- FS
48	1		*FRONT DOOR PILLAR INNER GARNISH (LOWER) CLIP LH	Not Necessary	80.00 FS	*- FS
49	2		*ROCKER PANEL SEALANT LH	Not Necessary	80.00 FS	*- FS
50	2		*CENTER PILLAR SEALANT LH (OUTER) SEALANT	Not Necessary	150.00 FS	*- FS
51	2		*SET CENTER PILLAR INNER GARNISH (LOWER) CLIP LH	Not Necessary	50.00 FS	*- FS
52	2		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
53	1		*SET REAR DOOR TRIM BOARD CLIP	Not Necessary	50.00 FS	*- FS
54	1		*REAR WHEEL TYRE	Not Necessary	250.00 FS	*- FS
55	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					20,306.50	7,171.60
- List Item Discount on L Items 20.00/20.00% (\$\$)					3,903.30	1,424.32
Total Parts (\$\$)					16,403.20	5,747.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,200.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,000.00
3	TUFF COAT	New	250.00	80.00
4	WIRING CHECK TAILLAMP	New	150.00	20.00
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	550.00	80.00
6	TRANSFER FRONT DOOR MECHANISM	New	150.00	60.00
7	REMOVE AND REFIX AUDIO SPEAKER	New	150.00	0.00
8	REMOVE AND REFIX REAR UNDERCARRIAGE	New	500.00	120.00
9	FOUR WHEEL ALIGNMENT	New	120.00	60.00
10	TRANSFER REAR DOOR MECHANISM	New	150.00	60.00
11	TO REMOVE/REFIT REAR FUEL TANK	New	150.00	0.00
12	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00

Gross Labour Cost (\$)

6,490.00

2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >