

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22012574/GQP3M4**Date:** 18/01/2023**REFERENCE**

Insured/Claimant:	LIANG CHEW HARDWARE PTE LTD	Policy No:	DMCVSNW00001132206		
Date of Loss:	10/12/2022	Nature of Claim:	OD	Claim No:	SNM22D208924/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE253B		Engine No:	6HK1663754
Make & Model:	ISUZU FVR34UUQDC, 7.8 D (M)		Chassis No:	JALFVR347E7000717
Reg. Date:	09/01/2015 (Man. Year: 2014)		Odometer:	0 km
Colour:	White			
Engine Capacity:	7790 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	295/80R22.5	Rear Tyre Size:	295/80R22.5
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
Nett Amount (S\$)	-2,000.00	-2,000.00	0.00	0.00

INSPECTION

Date of Assignment:	15/12/2022	Present Location:	Auto Insure Pte Ltd (HQ) (Woodlands)
Date Inspected:	16/12/2022	Inspected At:	Auto Insure Pte Ltd (HQ) (Woodlands) 6 Marsiling Lane Singapore 739145
Estimated Period of Repair:	0.0 days		

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$56,000.00
OMV :	\$60,440.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$55,011.00
COE Rebate (2) :	\$11,297.00
Total Rebate (1) + (2) = :	\$11,297.00

The total amount incurred will be Market Value \$56,000.00 minus Total Rebate \$11,297.00 = \$44,703.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Jan 2023)	
Parts:	N/A	ISUZU FVR34UUQDC 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE253B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >