

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012575/TQP3E2**Date:** 14/07/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00001132206

**Claimant Vehicle
No :** YM1907M**Insured Vehicle
No :** XE253B

Date of Loss: 10/12/2022

Nature of Claim: TP

Claim
No: SNM22D208924/C02/LEWLCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **YM1907M**

Make & Model: ISUZU FTR33P, 8.2 D (M)

Engine No: 6HH1410942

Reg. Date: 09/12/2005 (Man. Year: 2005)

Chassis No: JALFTR33P57000059

Colour: Blue

Odometer: 275928 km

Engine Capacity: 8226 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	10.00 R20	Rear Tyre Size:	10.00 R20 (D)
Front Left Side:	Aeolus 8 mm	Rear Left Side:	Aeolus 8/8 mm
Front Right Side:	Aeolus 8 mm	Rear Right Side:	Aeolus 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,280.00	6,897.00	7,383.00	51.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	100,950.00	80,200.00	20,750.00	20.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	115,230.00	87,097.00	28,133.00	24.41
Approved Total (Overridden) (S\$)		85,050.00		
(S\$)	115,230.00	85,050.00	30,180.00	26.19
+ GST 8.00/8.00% (S\$)	9,218.40	6,804.00	2,414.40	26.19
Nett Amount (S\$)	124,448.40	91,854.00	32,594.40	26.19

INSPECTION

Date of Assignment: 15/12/2022

Date Inspected: 21/02/2023 Inspected At:

Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721

Estimated Period of Repair: 13.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

LORRY REPAIR COST AT LUMP SUM \$8,000.00, 8 REPAIR DAYS;
TMA REPAIR COST AT \$77,050.00, 5 REPAIR DAYS.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Jul 2023)	
Parts:	N/A	ISUZU FTR33P 8.2 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YM1907M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S REAR HYDRAULIC STAND	Bent	3,800.00 F	*1,800.00 FL
2	1		*O/S REAR HYDRAULIC STAND HOSES	Bent	1,300.00 F	*650.00 FL
3	1		*O/S REAR MUDGUARD	Bent	750.00 F	*750.00 FL
4	1		*O/S TAILLAMP	Cracked	480.00 F	*480.00 FL
5	1		*O/S TAILLAMP BRACKET	Bent	300.00 F	*300.00 FL
6	1		*O/S BOOT COVER PANEL	Bent	3,000.00 F	*2,500.00 FL
7	1		*O/S BOOT COVER LOWER BEAM	Repair	1,500.00 F	*- FL
8	1		*O/S WING MIRROR ASSY	Cracked	1,200.00 F	*600.00 FL
9	2		*O/S PANEL HINGE	Repair	900.00 F	*- FL
10	1		*REAR PANEL HINGE	Bent	550.00 F	*250.00 FL
11	1		*LED WARNING LIGHT BAR	Cracked	500.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,280.00	7,630.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	733.00
Total Parts (\$\$)	14,280.00	6,897.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	450.00	0.00
2	WIRING CHARGES	New	300.00	50.00
3	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	3,500.00	2,200.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	1,200.00
5	A NEW UNIT OF SCORPION II, MODEL 10,000 TRUCK MOUNTED ATTENUATOR (TMA) INCLUSIVE OF STRUT, CATRIDGE WITH SIDE MOUNTED SUPPORT HYDRALIC MOTOR AND OPERATION ACCESSORIES	New	90,000.00	74,250.00
6	2MM ALUMINIUM REFLECTIVE SHEET OF TRUCK TAIL GATE	New	2,500.00	1,300.00
7	FULL LABOUR COST, DISMANTLING AND REMOVING OF DAMAGED TMA	New	2,000.00	1,200.00
Gross Labour Cost (\$\$)			100,950.00	80,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >